

ASS. REC. BY:

REF:

A/GI

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Veh No: SLA 9535 Yr Regn: 03, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.c. 1598Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 32777 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH1045468HGen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD / RIM orTyre Size: 205/55R16R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 8 mmL/Bal. 9 mmL/Bal. 8 mmD.O.A. 20/2/22D.O.I. 22/2/2022

Survey held at

Des. of Damages: Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX4894E
Accident Date : 20-Feb-2022

No. : 06542

Date : 22-Feb-2022

Our Ref : 022034 (AIG) / CHAN

PAGE : 1

YONG POY JOI @ YONG POY HONG
BLK 59 NEW UPPER CHANGI ROAD
#01-1274
Singapore 461059

*Not Withheld
11 Day &
Penny After Pain
6 days*

ESTIMATED COST OF REPAIR FOR TOYOTA ALTIS SLA9535S

1 pc	Boot lid		Ry	754.30	✓
1 pc	Boot lid inner lock		Mr	382.20	✓
1 pc	Boot lid rubber			166.40	✓
2 pcs	Boot lid hinge	@ S\$ 77.80	K	155.60	X
1 pc	Boot lid inner trim cover		Sn	349.30	X
2 pcs	Boot lid lamp	@ S\$282.30		564.60	✓
1 pc	Boot lid logo		Mr	52.20	✓
1 pc	Boot lid "COROLLA" emblem		Mr	42.40	✓
1 pc	Boot lid "ALTIS" emblem		Mr	44.20	✓
2 pcs	Taillamp	@ S\$363.10		726.20	✓
2 pcs	Taillamp lower bracket	@ S\$ 72.70		145.40	✓
1 pc	Rear end panel		Ry	581.20	✓
1 pc	End panel top garnish		Mr	229.40	✓
1 pc	Spare tyre panel			876.30	✓
1 pc	Spare tyre board cover			284.20	✓
1 pc	Spare tyre nut & screw		Sn	49.90	X
1 pc	Rear bumper fascia		Ry	482.20	✓
2 pcs	Rear bumper side retainer	@ S\$129.30	O.Y	258.60	✓
2 pcs	Rear bumper bracket	@ S\$ 52.20		104.40	✓
1 pc	Rear bumper reinforcement		Ry	420.20	✓
				6,669.20	
Less 25% :				1,667.30	

1 pc Rear bumper reverse sensor
1 pc Rear bumper clip

5,001.90 2005n
Not 300.00 sn
Mr 40.00 sn

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMX4894E

Page : 2

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

80.00 *601*

To putty and spray replaced parts

1,000.00 *8001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 *7001*

Total : S\$ 7,441.90

=====

Singapore Dollars Seven Thousand Four Hundred
and Forty One and Cents Ninety Only

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	125I

Vehicle Details

Vehicle No.:	SLA9535S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Feb 2022
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX556916
Chassis No.:	MR053REH104546888
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	23 Mar 2016
First Registration Date:	23 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,589.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2026
PARF Rebate Amount:	\$13,712.00

Intended COE Rebate Details

COE Expiry Date:	22 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,000.00
COE Rebate Amount:	\$18,375.00
Total Rebate Amount:	\$32,087.00

The information contained herein is correct as at 22 Feb 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/02/2022 19:23 (SGT)
Date of Accident 20/02/2022 11:05 (SGT)
Exact Location of Accident Singapore
Additional Location Information TAMPINES ST 41
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLA9535S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner YONG POY JOI@YONG POY HONG
NRIC No SXXXX125I
Email Address PJYONG1943@GMAIL.COM
Mobile Phone No (Phone) +65-97584321
Alternative Phone No +65-97584321

VEHICLE PARTICULARS

Manufacturer Toyota
Model ALTIS
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 0

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number GA444637
Cover Note Number -

DRIVER

Name of Driver YONG POY JOI@YONG POY HONG
NRIC No SXXXX125I

Date Of Birth	25/05/1943
Occupation	Indoor
Date Of Driving Pass	22/07/1969
Driving experience	52 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97584321
Alt. Phone Number	+65-97584321
Email Address	PJYONG1943@GMAIL.COM
Address	BLK 59 NEW UPPER CHANGI ROAD #01-1274
Address complement	-
Postcode	461059
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	LIM GEOK INN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMX4894E
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
NRIC No	PHOON KAI MUN
Contact Number	SXXXX662I
Address	(Phone) +65-90087975
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBL4245Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	VOKNESWARAN S/O ANBARASAN
NRIC No	SXXXX192D
Contact Number	(Phone) +65-97606297
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

YONG POY JOI @ YONG POY HONG

1/C 1820 1251 I

TIMES 11.05 AM 20-2-2022



Address BIK 59, NEW upper Changi Road
#01-1274 Spore 461059