



Service Request Details

Claim

S2M03TYS

Reference

CS3/ASM22001716/y3 

Loss Date

21 February 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

22 Feb 2022 2:20:58 PM

Request Date

22 February 2022

Due Date

1 March 2022

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work



Vehicle Information

Incident Vehicle Registration #
SJM1046A

Make
TPVD

Model
TOYOTA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHONG Lynn

lynn.khong@axa.com.sg
Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------

Document SubType

 Upload Documents

Already Attached

NAME	 SMJ1046A TP GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KUMAR Shailendra
DATE UPLOADED	22 February 2022

NAME	 WORKSHOP ADDRESS.msg.msg
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE UPLOADED	22 February 2022

NAME	 REPLY FROM TP.msg.msg
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE UPLOADED	22 February 2022

NAME	 GIA SH6746A INSD.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	KHONG Lynn
DATE UPLOADED	22 February 2022

NAME	 TP LIT PDF.pdf.pdf
------	--

AUTHOR	KUMAR Shailendra
DATE UPLOADED	22 February 2022

NAME	 TP LIT PRI EMAIL.msg.msg
TYPE	Legal
SUBTYPE	Others
AUTHOR	KUMAR Shailendra
DATE UPLOADED	22 February 2022
