



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22001730/Utf3z2 Date: 03/06/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 5376Z	Veh. Inspected	SLT 4194A	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007856/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI	Assign Date	23/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 318I LED (A)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8E36070NU81149	Colour	BLACK	
Odometer	62759 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45ZR18	MICHELIN	6 mm	
L/H Front Tyre	225/45ZR18	MICHELIN	6 mm	
R/H Rear Tyre	255/40ZR18	MICHELIN	6 mm	
L/H Rear Tyre	255/40ZR18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2020	Inspection Date	21/03/2022	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	