



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK			Ref: CS/ASM22001741/Aty3m4 Date: 06/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4474J	Veh. Inspected	SDQ 7722S	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M03U1O	Excess (\$)	0.00	
Assign From	ONG KIAN THENG DERICK	Assign Date	23/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS IS250	c.c	2500	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JTHBK262202023144	Colour	RED	
Odometer	212508 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	MICHELIN	6 mm	
L/H Front Tyre	225/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2022	Inspection Date	23/02/2022	
Survey held at	MCS GARAGE 10 KAKI BUKIT ROAD 2 #03-25 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	