

Scope Of Work Home Team Agency

SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following renairs:

CONTRACTOR:	STRIDES	VEH TYPE:	UNMARKED	UNIT:	CNB HQ	Reference No.	4067/CNB/4W/22/02/02
VEH NO:	VEH NO: SND4067U		REPAIR TYPE:		ACCIDENT		
EH MAKE/MODEL: HYUNDAI AVANTE		ODOMETER:		745	iLMS No.	-	

S/N		PARTS DESCRIPTION		QTY		Parts Cost Per Unit (8)	Total Parts Cost Per Unit (\$)
1			Scope Of Re	pairs			
1.1	Rear Bumper			1		544.50	544.50
1.2	Rear LH Bum	per Retainer CRACKED		1		30.25	30.25
1.3	Rear Lower B			1		387.20	387.20
1.4	Rear Bumper	Reinforcement DBFO RWEW		1		332.75	332.75
1.5	Rear Bumper	LHS Reflector CRACCES		1		48.40	48.40
1.6	Reverse Senso	or MYSIM (SHOWED)		1 /		169.40	169.40
1.7	Reverse Senso	or Wire Harness Miss (My CSHUKE)		1		242.00	242.00
1.8	Rear Number	Plate CRACICED DEFONIEUD		1		60.50	60.50
2			~	-/			
2.1		NA	\$0.00	0		0.00	0.00
Remarks: Pricing on this quotation is valid for Overseas Indentment. ETA:- 1-3 wee					Parts Total:	\$ 1,815.0	

S/N	LABOUR DESCRIPTION	Man-Hour Rate (S)	Man-Hour Qty	0.000	Ian-Hour st (\$)
1	Scope Of Repairs				
1.1	Remove, Replace & Spray Paint for Rear Bumper including replacing Rear LH Bumper Retain Bumper LHS Reflector & Rear Number Plate	ner, Rear 68.00	4 50	40	8.00
1.2	Remove & Replace Rear Bumper Reinforcement	68.00	10020	13	6.00
1.3	Remove & Replace Rear Lower Bumper	68.00	1	68	3.00
1.4	Replace & Wiring for Reverse Sensor & Reverse Sensor Wire Harness	68.00	0.5	68	3.00
		SUB-TOTAL	10	\$	680.00
2	Additional Services				
2.1	Collection Service From Station to Workshop (SOR 9)	61,20	1	61	.20
2.2	Return Service From Workshop to Station (SOR 9)	61.20	1	61	.20
		SUB-TOTAL	2	12	2.40
		La	bour Total:	\$	802.40
		GRA	VD TOTAL :	\$ 2	2,617.40
	Contractor shall complete the entire repair within 30 working days upon app	roval date . (Include parts awa	iting time)		

Verification of Scope of Work							
	Contractor QC		Vetted By:		Approved By:		
Nаше:	KONG SEW KUI	Name:		Name			
Date:	07.03.2022	Date:		Date:			
Sign:	Hote.	Sign:		Sign:			
	Verification of Completed Repairs						
	Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager		

Name:		Name:		Name	V.			
Date:		Date:		Date:				
Sign:		Sign		Sign.				
	All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made							

MITHOUT PRESURCE

ALLIANCE
A-PAC - PATRICL 97470950

NO AUTHORISATON

- SUBSECT TO PRINCIPAL APPROVAL (CONSISTENT)

- SUBSECT TO TO A agreement it applicable.

- 9/3/22 @ 3 m.

- 2/09455

- PART BY PART

- BY PAINT SURVEY.



Home Team Agency

SCOPE OF WORK

To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

	Reference No.
	iLMS No.

S/N	PART	TS DESCRIPTION	PARTED 2	QTY	Parts Cost Per Unit (S)	Total Parts Cost Per Ut Up (\$)	nit After Mark
1			Scope Of Rep	pairs			,
1.1	Rear LH Radar Sensor	- CAAUCEO.	THE BROWN	1	1294.70	1294.70	0
2			Additional Ser	rvices			
2.1		NA	是多量數類學是	0	0.00	0.00	
		ricing on this quotation is val ndentment. ETA:- Around 1 we			eas Parts Total:	\$	1,294.70

S/N	LABOUR DESCRIPTION			1/30/03/07	al Man-Hour Cost (\$)
1	Scope Of Repairs				
1.1	Remove, Replace & Function Test for Rear LH Radar Sensor	THE PERSON	N IZA		34.00
		SUB-TOTAL	0.5	\$	34.00
2	Additional Services				
2.1	Collection Service From Station to Workshop (SOR 9)	0.00	0		0.00
2.2	Return Service From Workshop to Station (SOR 9)	0.00	0		0.00
		SUB-TOTAL	0		0.00
		Labo	ur Total:	\$	34.00
		GRAND	TOTAL:	\$	1,328.70
	Contractor shall complete the entire repair within 15 working days upon approval date. (Inclu-	de parts awaiti	ng time)		
	Contractor shall provide Road Test & Health Check after CVR repair completed within 7 working day	s. (Include CM.	A repair if	anv)	

	Verification of Scope of Work								
			. c. meation of Scope of Work						
	Contractor QC		Vetted By:	Approved By:					
Name:	KONG SEW KUI	Name:	replie co	Name:					
Date:	20.06.2022	Date:	1. Mark	Date.					
Sign:	A STORY	Sign:	- 40 angpress	Sign:					
Verification of Completed Repairs									
	Contractor QC		Home Team QC / Fleet Manager / Appointed Surveyor		Home Team Contract / Fleet Manager				
Name		Name:		Name:					
Date:		Date:		Date:					
Sign:		Sign:		Sign:					