ASS. REC. BY: CS/ERIZZO	701776/EV43
The state of the s	GNMENT
From: Date:	Veh No: STE 19C Yr Regn: 27/8/15
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD ITPI WS ITP RES I OD RES I EVA I INV I MY	Truck / Trailer or
To Inspect Vehicle No:	Make: Mercedes -Benz CLA180 co 1595
at Workshop m/s	Colour 13/9() NC: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: WDD11730111 N 246 84:1
Claims No.	Gen. Cond: 2000 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / Strim / STD A/Rim or
~1	Tyre Size: F: 113/408 R
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	S JOUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Roort: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 6
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est Repairs: days Res.: Yes or No	D.O.A. 7,7 17 17 0 D.O.I. 8 3 17
Lum Sum: % 3 Val.: Yes or No	Survey held at Cycle & Cofficial
CA / REV / REP. / 24 HRS	Des. of Damages :Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	Т
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
- JYIY- / DA	
· · ·	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation:
Add	
2) Add P	: Interview (\$) Photos
Reper Formet:	:Tech, Invs (\$) Others
Lump Sum / I.B.I: (#)	:Weelend (\$
	TOTAL
ī,	

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SJE19C

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT 5 MAXWELL ROAD #17-00 TOWER BLOCK, MND COMPLEX SINGAPORE 069110

62239433

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

55177

/ 27/08/2015 SJE19C

WDD1173422N24684

27091030721540

MB/CLA 180 (C117) "URBAN"

021 191 Cosmos Blac/ 041 151-Leather Twi

		Date/Time Printed	CSE	Operator	THE REPRESENTATION OF THE PERSON OF THE PERS				
Account No	Terms			301 / Kerl	vn Ong				
VE000058	Credit	22/02/2022/ 17	Goods / Services		Qty	Unit Pric	e Disc%	Ar	nount
PEOUECT		Description			n 63 n mari	A 3/ II	N 83 A		OF
POLICY M POLICY M DRIVE IN DATE IN BY/AUTHR BPILAB DISASSEM BPIRES RESPRAY BPILAB USING XE IDENTIFI BPILAB TO REMOVI FRONT BU SPACER R	O/ACC DATE /EXCESS DATE SURVE IZED ON BLE AND REI FRONT BUMPI NTRY DIAGNI CATION STAI E, REPLACE I MPER X MPER COMPAI ING T BUMPER LI	2100426457-00 22/02/2022 // 22 22/02/202 // 22 22/02/202 // 22/02/202 // 22/02/202 // 22 22/02/202 // 22 22/02/202 // 22 22/0	OAMAGED PARTS FENDER ON CONTROL UNIT	2 0 8 REFINISH.	1.00 1.00 1.00 1.00 1.00	1431.9 63.9 6.9 49.1	0.10 1 00.00 9 00.00 7 00.00	960 800	1920.00 1800.00 380.00 120.00 1431.91 63.99 6.97 49.10 2646.06
			Cycl	Kerlyn Ong I ID: 6771 4420 HP: kerlyn.ong@cycle e & Carriage Indus ner Service Centre	9186 5113 carriage.com.sg	Steve 8/3/77 W	(LKK 1. 11.30 2. 11.30 1. 11.30		

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

Authorized signatory and company stampurvey

7% GST on

Nett 8418.03

8,418,03 589.26

Total Payable

9,007.29

Validity of this estimate is 14 days from date of quote interface combuter generated document, no signature is required.

Estimated costs quoted are excluding 151, We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after Managed for repairs or replacement. However, should this occur, we would advise your state in the state of the work payment for this may be made in cash, credit card or cheque. You must also agree the payping places the payping the paypin

Acknowledged by Repairer Signature:

Date:

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
 This Form must be completed by the Policyholder and/or the Authorised Driver
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this Point by insurance companies is not an admission of policy liability of the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

22/02/2022 16:31 (SGT) Date of Submission Date of Accident 22/02/2022 12:00 (SGT) Exact Location of Accident Singapore Additional Location Information STAR VISTA Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJE19C

INSURED/POLICYHOLDER

Is company? and the second s No Name Of Registered Owner LEE WENDY H. NRIC No SXXXX252D Fmail Address WENDY.TINGX@GMAIL.COM Mobile Phone No (Phone) +65-91916140 Alternative Phone No +65-91916140

VEHICLE PARTICULARS

Manufacturer Mercedes Model Cla180 Variant Exact purpose for which vehicle was being used at time of comment of the control of the contro Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte, Ltd. Type of Coverage Comprehensive Fleet Policy No Policy Number 2100426457-06 Cover Note Number

DRIVER

Name of Driver LEE WENDY H. SXXXX252D

Accident report SC1S222M0003

Page 1 of 13

See Catter Bank Line

1 (16)

Called Brick aller

Date Of Birth 05/09/1987 Occupation Indoor Date Of Driving Pass 15/09/2006 Driving experience 15 YEARS AND 5 MONTHS Gender Female Mobile Number (Phone) +65-91916140 Alt Phone Number +65-91916140 **Email Address** WENDY, TINGX@GMAIL, COM Address 1 WEST COAST WALK #01-02 Address complement Postcode 127158 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Hit and run / Vandalism / Damaged whilst parked Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? PASSENGER 1 **ROLAND CAMPBELL** Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number **GBK8356P** Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle

Accident report SC1S222M0003

Page 2 of 13

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or courteffer Ong Kai Li

DID: 6771 4420 HP: 9186 5113 Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Policyholder's Signature **Driver's Signature**


(If driver is not the policyholder) Date & Time 22/02/2022 1525

Name: KERLYN

Reporting Centre Personnel's

Date & Time

Version 1.3 | Updated 02 DEC 2020



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

STILL ON WHE	EN VEHICLE B	AT STAR VISTA E (GBK8356P) SUDE ONTO MY CAR.		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time 22/02/2022 1525

Driver's Signature

(If driver is not the policyholder)

Date & Time

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn Christing Cental Page, contest
Cycle & Chainge kerlyn anuan Loop
Customer Service Centre Y Manuan Loop

Cycle & Carriage Industries Pte Ltd

Version 1.3 | Updated 02 DEC 2020