

ASS. REC. BY: SteveREF: C83/LPC22000286/E993

PRS

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. 21/22/22/VC00/025341

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBF 4806K Yr Regn: 17/11/2016Type: M.Car / M.Cycle / Bus ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Hiace c.c. 2755Colour Silver A/C: Insured / Std / NI / NASp. Reading 133765 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFHT02P400710:368

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modl: Nil / S/Rlm / STD A/Rlm or \_\_\_\_\_

Tyre Size: F: P195R15CR: 11BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 7/1/22 D.O.I. 18/1/22Survey held at LYS Engineering

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NIO GIA report</u> <u>Repair range 4K-5K</u>
	<u>6 repair days</u>
25/01/22	Submit PRS
24/02/22	Submit final fig \$3852.30, 4 days (Red \$728.28, 16%)

Date/Time, File Pass to?

1) 24/02 Typist

Date/Time, File Return to?

2)

Report Format: TPLump Sum / I.B.I. (\$) 3852.30Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS \$

Photos

Others

TOTAL