

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AIG	DATE	: 22/03/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: TP CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMN5362U	Asher.	
MODEL	: HYUNDAI AVANTE 1.6		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 12-Jan-22
		TIME	: 1030HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 630.00	\$ 630.00 485
2	REAR BUMPER LOWER LID <i>Ken</i>	1	\$ 420.00	\$ 420.00
3	REAR BUMPER RETAINER <i>Ken</i>	2	\$ 62.40	\$ 124.80 35
4	REAR FENDER <i>Ken</i>	1	\$ 1,533.60	\$ 1,533.60

520
416

TOTAL PRICE	\$	2,708.40
LESS 20%	\$	541.68
SUB TOTAL PRICE	\$	2,166.72

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>Ken</i>	1	\$ 20.00	\$ 20.00
2	SPORT RIM <i>Ken</i>	1	\$ 1,000.00	\$ 1,000.00 450

470

TOTAL	\$	1,020.00
-------	----	----------

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	

3	TO APPLY RUST PROOFING AND TUFF COAT	\$ 250.00	30	
4	WIRING CHECK	\$ 60.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
6	FOUR WHGEEL ALIGHMENT	\$ 100.00	80	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 40.00	X	

TOTAL

\$2,530.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,186.72
TOTAL LABOUR COST : \$ 2,530.00
TOTAL REPAIR COST : \$ 5,716.72

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

FAX :

Adrian L
~~1/8~~ 4/5 02
total: 1626
4/5: 1.31c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: