



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP22001812/Utf3e2	
BLK 1 KAKI BUKIT AVE 6			Date: 07/03/2022	
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883				
ON BEHALF OF CHEOW PEE YONG DORIS			Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SKQ 6452U
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		25/02/2022
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ASX 2.0 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JMFXTGA2WFZ005588	Colour	BLUE	
Odometer	261977 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	HABILEAD	6 mm	
L/H Front Tyre	215/60 R17	HABILEAD	6 mm	
R/H Rear Tyre	215/60 R17	HABILEAD	6 mm	
L/H Rear Tyre	215/60 R17	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		21/02/2022	Inspection Date	
			25/02/2022	
Survey held at		BLUWEL AUTOMOTIVE SERVICE PL		
		BLK 1 KAKI BUKIT AVE 6		
		#01-28/53/55/56 (MAIN OFFICE)		
		SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	