# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 25/02/2022 09:11 (SGT) Date of Accident 24/02/2022 12:05 (SGT) Exact Location of Accident Singapore Additional Location Information PIE TWDS CHANGI B4 THOMSON ROAD EXIT Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBK8439J

#### INSURED/POLICYHOLDER

Is company? Name Of Registered Owner ATECH FACILITY MAINTENANCE PTE LTD Company Reg No 2XXXXX037R **Email Address** abc8627e@gmail.com Mobile Phone No (Phone) +65-64485464 Alternative Phone No (Office) +65-64485464

# VEHICLE PARTICULARS

Manufacturer

Nissan Model Nv200 Variant Exact purpose for which vehicle was being used at time of **Employment** accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle Transmission Auto CC 1597

# **INSURANCE COMPANY**

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number DMCVSNW00151692101 Cover Note Number

# DRIVER

Name of Driver KO HOCK CHIN NRIC No. SXXXX917E

Date Of Birth 27/09/1974 Occupation Indoor Date Of Driving Pass 31/12/2007 Driving experience 14 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-97598225 Alt. Phone Number Email Address abc8627e@gmail.com Address BLK 369 BUKIT BATOK ST 31 Address complement #03-503 Postcode 650369 Is the driver the policyholder? Nο If No. Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions AFTER RAIN Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name JOHNSON ONG Gender Male PASSENGER 2 Name DARRYL TAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLS REFER TO THE ATTACHED STATEMENT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** 

**GBC5140G** 

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# INJURED PERSONS DETAILS

# INJURED 1

Name of injured person Gender	KO HOCK CHIN Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BODY
Injured person in which vehicle?	GBK8439J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time la

Driver's Signature (If driver is not the policyholder) / Date & Time

Sym 35/02/12 Witnessed by Reporting Centre

Personnel

## Sketch Plan



		/
		<u>/</u>
	Refer to attached	
	Ketel to anlacyto	
1		
/		

# Declaration

I/We declare the foregoing particulars are true in every respect,



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

On 24.02.22 at about 12:05 hours at along PIE towards Changi (Before Thomson Road Exit). I was travelling on the lane 2 , i slow down and stop my vehicle due to front vehicle breakdown.

Suddenly I heard a loud bang and great impact from behind and when I alighted I realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my vehicle. I wish to state that I have two passengers inside the vehicle.

Vehicle (A): GBK8439J

Vehicle (B): GBC5140G

















