

Immediate Advice

To: AXA Insurance Pte Ltd 24/3/2022

Survey Details:

Date of loss	22-Feb-22	
Date of appointment	25-Feb-22	
Date of survey	25-Feb-22	
Location of survey	H S AUTOMOTIVE SERVICES	

Vehicle Details:

Claim Type:	Third Part	y Claim	
Vehicle number	SKT 8816	4	
Make and Model	MAZDA 3	4-DOOR SEDAN 1.5L	SP 6EAT
Date of registration	25/6/201	5	
Excess	-		
Market Value	\$	36,000.00	
Parf Rebate	\$	23,329.00	
Nett Loss	\$	12,671.00	

Repair details:

Initial Estimate	Ś	4,044.40
illitiai Estilliate	۲	4,044.40

Proposed/Revised repair cost:

Parts	\$ 934.40
Check items (estimate)	\$ -
Labour	\$ 460.00
Total	\$ 1,394.40
Lump Sum(if applicable)	\$ 1,100.00

Number of days for repair	<u>2</u>



Remarks:

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	