

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AO I ONIOBILE INOI				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC22001827/Vty3n2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 1 189556				14-03-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKP 4466Z	Veh. Ir	spected	SH 6693T	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1161316-002	Exces	s (\$)	0.00	
	Assign From		Assigr	n Date	09/02/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093511	Colou	•	BLUE	
	Odometer	836897	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	206/60 R16	WEST I	_AKE	5 mm	
	L/H Front Tyre	206/60 R16	WEST		5 mm	
	R/H Rear Tyre	206/60 R16	WEST I		5 mm	
	L/H Rear Tyre	206/60 R16	WEST I	_AKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/02/2022	Inspec	tion Date	09/02/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					