

ASS. REC. BY: Kim

REF:

CC4/LPC22001828/Rgs3

577B

COE RPRY = 2021/Jun

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMX 6204Jat Workshop m/s STUTTGART AUTOof 27A TANJONG Pagar JURNInsured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 128k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMX 6204J Yr Regn: 2007/JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche 987 Boxster S Tip c.c. 3387Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 77280 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP 022298 2747-22153Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40ZR18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. _____ mmL/Bal. 6 mm L/Bal. _____ mmD.O.A. 19/02/22 D.O.I. 03/03/22Survey held at STUTTGARTDes. of Damages B / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 102K

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Rep. Format: _____

Lump Sum / L.B.A. (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	577B
Vehicle No.:	SMX6204J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2022
Vehicle Make:	PORSCHE
Vehicle Model:	PORSCHE 987 BOXSTER S TIPTRONIC
Primary Colour:	Yellow
Secondary Colour:	Black
Manufacturing Year:	2007
Engine No.:	67707752
Chassis No.:	WPOZZZ98Z7U722153
Maximum Power Output:	217.0 kW (290 bhp)
Open Market Value:	\$90,988.00
Original Registration Date:	12 Jun 2007
First Registration Date:	12 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$100,087.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,347.00
COE Rebate Amount:	\$25,552.00
Total Rebate Amount:	\$25,552.00

The information contained herein is correct as at 03 Mar 2022

OK

Porsche Boxster S 3.4A Tip (COE till 01/2027)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

Price **\$118,800**

Depreciation  \$24,170 /yr Reg Date 31-Jan-2007
(4yrs 10mths 27days COE left)

Mileage 135,000 km (8.9k /yr) Manufactured  2006

Road Tax  \$4,488 /yr Transmission Auto

Dereg Value  \$25,883 as of today (change) OMV  \$98,498

COE  \$52,660 ARF  \$108,348

Engine Cap 3,387 cc Power 217.0 kW (290 bhp)

Curb Weight  1,395 kg No. of Owners 5

Type of Vehicle Sports Car