

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	▼	📄	▼	🖨	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	---	---	-------------



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (S) PTE LTD		Ref: CS/MSG22001836/Utf3		
4 SHENTON WAY #21-01		Date: 25/02/2022		
SGX CENTRE 2 SINGAPORE 068807		Code: MSG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	GX 8823E	<b>Veh. Inspected</b>	FBP 3512L	
<b>Policy No.</b>	30001762924	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	269846	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	MERIMEN (NOR AZIAN BINTE NOORDIN)	<b>Assign Date</b>	25/02/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	<b>c.c</b>		0	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>		
<b>Chassis No.</b>	<b>Colour</b>			
<b>Odometer</b>	-	<b>Steering</b>		
<b>Brakes</b>	<b>Modification</b>			
<b>General</b>				
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>			mm	
<b>L/H Front Tyre</b>			mm	
<b>R/H Rear Tyre</b>			mm	
<b>L/H Rear Tyre</b>			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
<b>Accident Date</b>	14/02/2022	<b>Inspection Date</b>	28/02/2022	
<b>Survey held at</b>	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				