

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|   | Reg. No: 199607198R GST Reg. No. 19-9607198-R  |   |                 |                       |  |
|---|--|---|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                       |  |
|   | AUTO & GENERA  | L INSURANCE (S) PL  | Ref:            | CS/AGI22001845/Utf3n2 |  |
|   |  | TINSURANCE)<br>U AVENUE #03-01<br>PPING CENTRESINGAPORE           | Date            | 02/06/2022            |  |
|   |  |   | Code            | : AGI                 |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |  |   |                 |                       |  |
|   | Insured Veh.   | SGS 994Z  | Veh. Inspected  | SLT 8774A             |  |
|   | Policy No.   |   | Coverage (\$)   | 0.00                  |  |
|   | Claim No.  | C10014039 /CD   | Excess (\$)     | 0.00                  |  |
|   | Assign From  | SHAFAWATI   | Assign Date     | 28/02/2022            |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                       |  |
|   | Make & Model   | HYUNDAI AVANTE (A)  | c.c             | 1591                  |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    | 2009                  |  |
|   | Chassis No.  | KMHDU41BR9U751986   | Colour          | BLACK                 |  |
|   | Odometer   | 232066 KM   | Steering        | IN ORDER              |  |
|   | Brakes   | IN ORDER  | Modification    | SPORTS RIM            |  |
|   | General  | GOOD  |                 |                       |  |
| 3. Conditions of Tyres  |  |   |                 |                       |  |
|   |  | Size  | Make            | Balance               |  |
|   | R/H Front Tyre   | 215/45 ZR17   | KAPSEN          | 6 mm                  |  |
|   | L/H Front Tyre   | 215/45 ZR17   | KAPSEN          | 6 mm                  |  |
|   | R/H Rear Tyre  | 215/45 ZR17   | TOYO            | 6 mm                  |  |
|   | L/H Rear Tyre  | 215/45 ZR17   | TOYO            | 6 mm                  |  |
| 4.  | Description of Damages   |   |                 |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  DAMAGES SEE DETAILS.   |   |                 |                       |  |
|   |  |   |                 |                       |  |
| 5.  | General Information  |   |                 |                       |  |
|   | Accident Date  | 20/02/2022  | Inspection Date | 04/03/2022            |  |
|   | Survey held at   | FASTECH AUTO PTE LTD  |                 |                       |  |
|   |  | 1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                       |  |
| 5a.   | 5a. Remarks  |   |                 |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                       |  |
| 5b.   | Estimate Days of Repair  |   |                 |                       |  |

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: