

Your Ref: SNM22D201350/C02/THAMYL

Date: 05th Oct 2022

Our Ref: CS1/CTI22001854/Twy3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GW 2233C**INSURED VEHICLE: GV 9904J****ACCIDENT DATE: 20/01/2022**

We thank you for your instruction on 29/09/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GW 2233X from M/s Aeon Auto Consultants LLP.
- b) Singapore Accident Statement of Vehicles GW 2233C and GV 9904J.
- c) Final Repair Bill of GW 2233C from M/s U883Detailing Pte Ltd.
- d) Colour damaged vehicle photographs of GW 2233C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GW 2233C
Make & Model	: Nissan Urvan
Year of Registration	: -
Chassis Number	: JN1MG4E25Z0793924
Engine Capacity	: 2953 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.