


ASS. REC. BY: Taufik

REF: es/AG122001859/7173 -Tny3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 860K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: GBL 2964T Yr Regn: 2021 14 April
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Nissan NV200 1.6 4 C.C. 1598
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 12585 T/Radio: Insured / Std / NI / NA
Eng/No: JW1944M 2020001756
C/No: _____
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 165/80R14
R: 2-
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front
R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. _____
Survey held at Yew Tee Auto
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/09/22 Taufikh confirmed final fig: \$5533.17
and 7 days
(red, 4767. 46%)

Date/Time, File Pass to? ☐ : Preli. Report
1) 30/09/22 ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 7
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
\$ + RS. \$ _____
Photos _____
Others _____
TOTAL _____

Report Formed: _____
Lump Sum / L.B.L. (\$ 5533.17)