



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22001859/Tny3m4 Date: 10/10/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SML 4411D	Veh. Inspected	GBL 2964T
Policy No.		Coverage (\$)	0.00
Claim No.	C10013519/KY	Excess (\$)	0.00
Assign From	SHAFAWATI	Assign Date	28/02/2022
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200 1.6 A	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JN1YAAM20Z0001756	Colour	BLACK
Odometer	12585 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	6 mm
L/H Front Tyre	165/80 R14	TOYO	6 mm
R/H Rear Tyre	165/80 R14	TOYO	6 mm
L/H Rear Tyre	165/80 R14	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/01/2022	Inspection Date	04/03/2022
Survey held at	39 Woodlands Close #01-12, Mega@Woodlands		
Repairer	YEW TEE AUTOMOBILE TECH PL (HQ)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	