

ASS. REC. BY:

REF:

AWA/ 220018861/K4322

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBH 27927

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Citroen Dispatch

c.c

1560

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

200314

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF 7VBBH SHG 2 058652

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

11/2/22

D.O.I.

2/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/13 21:00 @ 4050L Canhu (Red. \$ 2664.50, 40%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : **ODWR**Vehicle No. : **GBH2792T**Make & Model : **CITROEN DISPATCH L1 1.6**Year of Manufacture : **2016**Chassis No. : **VF7VBBHSHGZ058652**Ins Company : **ALLIED WORLD**Engine No. : **10JBHK0001046**

Excess : _____

Policy No. : **BVFCB0013732102**Date of Accident : **11.02.2022**Time of Accident : **10:50HRS**

Suggested Days of Repair : _____

In-house Vehicle Assessor : _____

Repair EstimatesParts (a) Cost / List Price Items \$ **4,045.00**Plus/Less 10% \$ **404.50**Total of Cost / List \$ **4,449.50**(b) Nett Price Items \$ **-**

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ **365.00****Total Parts Cost (Appendix A) \$ 4,814.50****Labour (Appendix B) \$ 1,900.00****Total Repair Cost \$ 6,714.50**

The above total will be subjected to 7% G.S.T.

Case Owner : **ROHANI**

Signature : _____

Contact No : _____

NOT Notified
11 Day @
Repair After Pain
Ex @ 1500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Name of Surveyor : **Henrich**Company : **LKK**Survey conducted on : **2/3/22** at **11am****Remarks By Surveyor**(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : **05** day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : **Le** Date: **2/3/22**

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBH2792T Case Owner : ROHANI

Make & Model : CITROEN DISPATCH L1 1.6 Year Manufacture : 2016

Chassis No : VF7VBBHSHGZ058652 Engine No : 10JBHK0001046

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : ODWR

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper <i>Del/Gro</i>	1	\$ 450.00				✓
	Rear bumper clip <i>Ne</i>	10	\$ 20.00				✓
3	LH Front Door <i>Ry</i>	1	\$ 1,150.00				✓
4	LH Front Door Protector <i>Del</i>	1	\$ 85.00				✓
5	LH Rear Door <i>Ry</i>	1	\$ 1,900.00				✓
6	LH Rear Door Protector <i>Del</i>	1	\$ 150.00				✓
7	LH Door Side Rubber seal <i>Plu</i>	1	\$ 140.00				X
8	RH Rear Wheel Cover <i>miy</i>	1	\$ 150.00				✓
9	Company Sticker	1			<i>Ne</i> \$ 15.00		✓
10	Wording Sticker-LOGO WARBURG <i>Ne</i>	1	<i>(Check Inland or not)</i>			\$ 350.00	✓
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	6					
16	0	1					
	0	1					
18	0	11					
19	0	1					
20	0	1					
21	0	1					
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax:62844284,62815767

Vehicle No.	: <u>GBH2792T</u>	Case Owner	: <u>ROHANI</u>
Make & Model	: <u>NISSAN DISPAATCH L1 1.6</u>	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.