

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001913/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	16/03/2022	
	ATTN: ONG KIAN	THENG DERICK		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 1048X	Veh. Inspected	ł	GBJ 9954L	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03UHX	Excess (\$)		0.00	
	Assign From	ONG KIAN THENG DERICK	Assign Date		01/03/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFHT02P600249706	Colour		WHITE	
	Odometer	93472 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	HANKOOK		5 mm	
	L/H Front Tyre	195 R15C	HANKOOK		5 mm	
	R/H Rear Tyre	195 R15C	HANKOOK		5 mm	
	L/H Rear Tyre	195 R15C	HANKOOK		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information					
	Accident Date	22/12/2021	Inspect Date /	Time	01/03/2022 ( 04:00 PM )	
	Survey held at	3011 BEDOK IND PARK E #01-2	2006			
	Repairer	Repairer COSMOPOLITAN ENGRG. SERVICES PTE. LTD.				
5a.	Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22001913/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser