

ALY

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

NOTE (48)

Date: 28.02.2022  
Time: 11:12:02  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305506812  
REGN NO : SHD3249P  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ  
DATE OF REGN : 24.02.2017  
DATE/TIME IN : 28.02.2022 09:35  
ACCIDENT DATE : 26.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|      |                   |                           |     |        |       |        |                    |            |
|------|-------------------|---------------------------|-----|--------|-------|--------|--------------------|------------|
| 0001 | 04-01-0104-2566-G | GRIP-FRONT DOOR OUTSIDE R | 1   | 234.80 | 20.00 | 187.84 | ent                | ✓          |
| 0002 | 04-01-0104-2470-G | MOULDING ASSY-W/LINE RR D | 1   | 166.20 | 20.00 | 132.96 | ent                | ✓          |
| 0003 | 04-01-0104-2468-G | MOULDING ASSY-W/LINE FRT  | 1   | 110.10 | 20.00 | 88.08  | ent                | ✓          |
| 0004 | 04-01-0104-0810-G | MOULDING ASSY-SIDE SILL R | 1   | 290.00 | 20.00 | 232.00 | RY                 | 511 110    |
| 0005 | 28-01-0103-0003-A | FRT DOOR LOGO CTPL        | 1 N | 75.00  | 10.00 | 67.50  | ent                | 20% 408.88 |
|      |                   |                           |     |        |       |        | SUB-TOTAL : 708.38 |            |
|      |                   |                           |     |        |       |        | 155                |            |
|      |                   |                           |     |        |       |        | 10% -139.50        |            |

JOB NATURE

|      |    |                   |        |        |  |  |                      |
|------|----|-------------------|--------|--------|--|--|----------------------|
| 0000 | PB | PANEL BEATING     | 700.00 | 525    |  |  |                      |
| 0001 | SP | SPRAYPAINT CHARGE | 600.00 | ✓ 1125 |  |  |                      |
|      |    |                   |        |        |  |  | 1673.38              |
|      |    |                   |        |        |  |  | SUB-TOTAL : 1,300.00 |
|      |    |                   |        |        |  |  | 45\$ 1350            |
|      |    |                   |        |        |  |  | TOTAL : 2,008.38     |
|      |    |                   |        |        |  |  | 2 days *             |

Jumari  
MVA NAME & SIGNATURE  
DATE: 28/2/22

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE:

Tamhin 97415749  
up? 28/2/22 C415  
45 Rosny after repair  
2 days  
Tamhin Chhandum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: