

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LIBERTY INSURAI	NCE PL	Re	ef:	CS3/CWF22001964/Vvy3e2	
	PTE LTD	& COMPANY INTERNATIONAL AY, #19-10 OUE DOWNTOWN2 09	Da	ate:	07/06/2022	
			Co	ode:	LIP	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	tree branch fell	Veh. Inspected		SLV 4391L	
	Policy No.	1095870/G/KY	Coverage (\$)		0.00	
	Claim No.	ALS22/0006	Excess (\$)		0.00	
	Assign From	KENNETH YEE	Assign Date		02/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA NIRO	c.c		1580	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KNACC81CVJ5149528	Colour		BLUE	
	Odometer	36307 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/50 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	225/50 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	225/50 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	225/50 R17	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE ROO		OFTOP.			
5.	5. General Information					
	Accident Date	07/02/2022	Inspect Date / Tim	ne	02/03/2022 ( 05:00 PM )	
	Survey held at CAR CITY AUTO CENTRE PTE LTD					
	BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.	Estimate Days of Repair					

Report Ref No. CS3/CWF22001964/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days