



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22001965/Kvy3n2 Date: 18/03/2022 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 9294X	Veh. Inspected	JSL 8229
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10014083/JM	Excess (\$)	0.00
	Assign From	FRAULEINE KHOO	Assign Date	02/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA BR-V (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	PMHDG1840HD912991	Colour	WHITE
	Odometer	119574 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	YOKOHAMA	8 mm
	L/H Front Tyre	195/60 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	195/60 R16	YOKOHAMA	4 mm
	L/H Rear Tyre	195/60 R16	YOKOHAMA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/02/2022	Inspection Date	07/03/2022
	Survey held at	5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405		
	Repairer	MASSIVE TRADING & AUTO		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	