

CS3/11/22001980/Rtn 3

06 Jun 2016

Veh No: SLD 1724 Yr Regn: 1

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

.Truck / Trailer or

Make: HONDA VIZU c.c 1496

Colour BLACK A/C: Insured / Std / NI / NA

Sp. Reading 2576 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU21130316

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

	
N/S	O/S
	

Tyre Size: F: 215/60R16

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or CBW/ERO

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 7 mm

L/Bal. mm L/Bal. mm

D.O.A. 02/03/72 . D.O.I. 02/03/72

Survey held at AT PERFORMANCE

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop orDes. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

TOTALThis image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. On the left side, there is a vertical margin line, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled document. There is no handwriting or printed text on the page.