

MOTOR SURVEY ASSIGNMENT

Date	02/03/2022	Our Ref No.	D22000621MFCV
Accident Date	25-02-2022	Claim Type	Third Party
Insured Vehicle	GBD5670M	Third Party Vehicle	SKS2999A
Survey Location	CHENG HOE MOTOR PTE LTD BLK 1019 YISHUN IND. PARK A #01-374 (S) 768761	Contact Person	DORLYN LI
Contact No.	64812001	Fax No.	64821296

Survey Type Without Prejudice

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD
Contact Person	Fax No. 68416315
Contact Number	62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention	DORLYN LI
Officer Incharge	ESTHER		

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.