

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001982/Bvy3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	01/04/2022	
	ATTN: ONG KIAN	THENG DERICK		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKT 9963B	Veh. Inspected	k	SLS 5418D
	Policy No.	GA364707	Coverage (\$)		0.00
	Claim No.	S2M03U8D	Excess (\$)		0.00
	Assign From	ONG KIAN THENG DERICK	Assign Date		02/03/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	MAZDA 6 2.0	c.c		1998
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	JM6GL1071H0123800	Colour		WHITE
	Odometer	91680 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/55 R17	YOKOHAMA		5 mm
	L/H Front Tyre	225/55 R17	YOKOHAMA		5 mm
	R/H Rear Tyre	225/55 R17	YOKOHAMA		5 mm
	L/H Rear Tyre	225/55 R17	YOKOHAMA		5 mm
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	E SUSTAINED DAMAGES AT THE N/S BODY AND FRONT			
5.	General Information				
	Accident Date	23/02/2022	Inspect Date /	Time	02/03/2022 (01:39 PM)
	Survey held at CELEBRITY AUTO				
	BLK 176 SIN MING DRIVE #03-18 SIN MING AUTOCARE SINGAPORE 575721				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001982/Bvy3e2

Inspected By

Am

LIM TEOW GUAN

MV.

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser