



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM21012131/Tty3e2-1 Date: 26/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHB 4271C	Veh. Inspected	SMY 4141P
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03N5A	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	02/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GK82101964	Colour	GREY
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	27/11/2021	Inspection Date	14/03/2022
	Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	