

REF:

ASSIGNMENT

Veh No: SMY 4266K Yr Regn: 2017 / Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Harbor Freight C.C. 1496

Colour 360 A/C: Insured / Std / NI / NA

Sp. Reading 209326 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 6811070316 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or Rapid

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 26 mm L/Bal. 0,6 mm

D.O.A. D.O.I. 01/03/22

Survey held at MK Solution | 1

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

TP Shima

MY :

PV:

Nett:

883W

☐: Prel. Report

☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Report Format :

Learner: GARY HOPKINS

☐ Interview (\$

□ Tech Invs (3)

March 19

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

Photos

Others