

ASS. REC. BY:

REF: MSG/22002005/kqy3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hui

of _____

Insured: 187M

Policy No. _____


Claims No. MSC/V/22-000044

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 860K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

15/06/22 @ 5.26pm revised to Nor Azian via merimen.

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Veh No: GBL 6137M Yr Regn: 11.21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A)Make: NIS NV36 CERVAN C.C. 1988Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 13922 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VR 2 E 26136529Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NIJ / S/Rlm / STD A/Rlm orTyre Size: F: 195/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 22/2/22

Rear

R/Bal. 2 mmL/Bal. 2 mmD.O.I. 17/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 22/02/2022

TP Veh Reg No: FBH6825G

Estimate No: ES2290484/AMK

Date: 13 May 2022

Policy No: 5124527050 PREFERRED

Veh Reg No: GBL6137M

Make/Model: NISSAN NV350

Chassis No: VR2E26136529

Engine No: QR20020160R

Reg. Date: 15/11/2021

*Not Authorized
 Repair By paint
 2 days*

Estimate Repair Cost to Vehicle No :GBL6137M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	733.90	1 PC	733.90	✓
2 REAR BUMPER CLIP	4.40	5 PC	22.00	✓
3 TAILGATE LOGO	71.40	1 PC	71.40	X
4 TAILGATE EMBLEM 'CARAVAN'	110.00	1 PC	110.00	X
5 TAILGATE EMBLEM 'NV350'	121.00	1 PC	121.00	X
			1,058.30	
		Less 10%	105.83	952.47
Special Net				
6 REVERSE SENSOR	200.00	1 PC	200.00	✓
7 TAILGATE STICKER '70KM/HR'	10.00	1 PC	10.00	X
8 TAILGATE STICKER '8 PAX'	10.00	1 PC	10.00	X
			220.00	220.00
Labour				
9 REMOVE & REFIX REAR BUMPER & ATTACHMENTS;KNOCKING & REPAIR REAR END PANEL & REALIGN TAILGATE THE SAME	400.00	1 LA	400.00	200
10 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS,TAILGATE,REAR END PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	200
			1,000.00	1,000.00
			Total	S\$ 2,172.47
			Add GST @ 7%	152.07
			Total Amount Payable	S\$ 2,324.54

* SURVEY VEHICLE AT KIO WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

og

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 23/02/2022 17:16 (SGT)
Date of Accident 22/02/2022 16:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information SERANGOON ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBL6137M

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner UTOPIA PRESIDUM PTE LTD
Company Reg No 2XXXXX187M
Email Address andy.ng@utopiasg.com
Mobile Phone No (Phone) +65-98530053
Alternative Phone No +65-98530053

VEHICLE PARTICULARS

Manufacturer Nissan
Model Caravan
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 0

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5124527050 PREFERRED WSHOP PLAN
Cover Note Number 15/11/2021 - 14/11/2022

DRIVER

Name of Driver CHUA TZE HWA (XIE ZHIHUA)
NRIC No SXXXX507H

A hand-drawn map showing the intersection of Swanigan Rd and Right Rivershutes. A north arrow points upwards. A circle labeled 'B' is located on the left side of the map. A building labeled 'A' is situated at the intersection. Two arrows point upwards along the road from the bottom of the map.

A: GBL 6137M
(alone)

B: FBH 68256
Selam S10 Lampiran
S1582407E

Vehicle No: GBL 6137M (NTMC)
Date & Time: 22/02/2022 @ 1630 (clear day)

I was driving on the extreme right lane of ~~the~~ Serangoon Rd when I felt a sudden impact on my rear and realised. Motor bike FBH 68256 had hit onto the back of my van & thereafter fell down to the ground. I alight from my vehicle, check on ~~the~~ the rider, rider informed that he felt pain on his leg but still movable. As such, we exchanged particulars & left the scene. That's all.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: (Amk)
NRIC/FIN No.: _____

() Claim Own Policy ☒ Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()