

Your Ref: 19.27368

Date: 30th Mar 2022

Our Ref: CS1/LAW22002046/Uqy3e2

M/s Axa Insurance Pte Ltd
C/o Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKU 2207S
INSURED VEHICLE: SJS 4616D
ACCIDENT DATE: 10/04/2019

We thank you for your instruction on 04/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKU 2207S from M/s MC-COY Appraiser Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Singapore Accident Statement of Vehicles SKU 2207S and SJS 4616D.
- d) Police Report of Vehicles SKU 2207S.
- e) Colour damaged vehicle photographs of SKU 2207S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKU 2207S
Make & Model	: Honda S2000 2.2 M
Chassis Number	: F22C1010226
Year of Registration	: 2008
Engine Capacity	: 2156 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.