

ASS. REC. BY: Taufik

REF:

INC NS/INC22002058/Tqc

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. MT/1163711-003  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 6 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SHB113GE Yr Regn: 2021, Sep  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: MG MG5 EV C.C. 120 KM  
Colour: Green A/C: Insured / Std / NI / NA  
Sp. Reading: 49982 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: LSJE2403646051399  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 205/60R16  
R: 205/60R16  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Fallen  
Front R/Bal. 6 mm  
L/Bal. 6 mm  
D.O.A. \_\_\_\_\_  
Survey held at SURT WL  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S Frt, 14/C  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised final fig \$6470.24, 6 days. (Red \$23381.44, 78%)

Date/Time, File Pass to?

1) 06/04 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format :

TP

Lump Sum / L.B. (C) 6470.24

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS. ☐ SI

Photos

Others

TOTAL



## Case Details

Case Reference Number : TAX/03/22/2004  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1136E

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-17636-ID  
 Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd  
 Accident Date and Time : 02/03/2022 05:07 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BRACKET-F/FDR FRT LWR -LH	1	15.80	15.80	10.00	14.22	Replace	0	0	Not Give	fun
One Time Key In	Main			INSULATOR ASM-F/FDR -LH	1	29.22	29.22	10.00	26.30	Replace	0	0	Check	?
One Time Key In	Main			INSULATOR ASM-F/FDR MID -LH	1	8.94	8.94	10.00	8.05	Replace	0	0	Check	?
One Time Key In	Main			LINER ASM-FRT W/H - LH	1	125.22	125.22	10.00	112.70	Replace	1	112.70	Replace	de✓
One Time Key In	Main			PANEL ASM-H/PLR INR - LH	1	340.80	340.80	10.00	306.72	Replace	0	0	Not Give	Xun
One Time Key In	Main			PANEL ASM-COWL SI -LH	1	493.00	493.00	10.00	443.70	Replace	0	0	Not Give	fun
One Time Key In	Main			RAIL ASM-F/CMPT SI - LH	1	1,380.70	1,380.70	10.00	1,242.63	Replace	0	0	Check	?
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	?
One Time Key In	Main			WHEEL FRONT LH	1	618.08	618.08	10.00	556.27	Replace	1	556.27	Replace	cut✓
One Time Key In	Main			COVER ASM-WHL TR	1	8.94	8.94	10.00	8.05	Replace	1	8.05	Replace	cut✓
Total Spare Part Cost									16,157.71	Surveyor Total 3,245.39				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									16,157.71	Final Sur Total 3,245.39				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ARM ASM-FRT LWR CONT - LH	1	400.92	400.92	10.00	360.83	Replace	0	0	Check	?
One Time Key In	Main			LINK-FRT STAB SHAF - RH/LH	1	99.52	99.52	10.00	89.57	Replace	0	0	Check	?
One Time Key In	Main			KNUCKLE ASM-STRG - LH	1	252.40	252.40	10.00	227.16	Replace	0	0	Check	?
One Time Key In	Main			BEARING - S/KNU / BEARING-FRT SUSP STRUT MT	1	452.08	452.08	10.00	406.87	Replace	0	0	Check	?
One Time Key In	Main			NUT-FRT WHL DRV SHAF	1	9.88	9.88	10.00	8.89	Replace	0	0	Check	?
One Time Key In	Main			STRUT-FRT SUSP - LH	1	522.28	522.28	10.00	470.05	Replace	0	0	Check	?
One Time Key In	Main			MOUNT ASM-FRT SUSP STRUT	1	184.28	184.28	10.00	165.85	Replace	0	0	Check	?
One Time Key In	Main			GEAR SUB ASM-STRG	1	980.00	980.00	10.00	882.00	Replace	0	0	Not Give	Xun
One Time Key In	Main			ROD ASM-STRG LNKG OTR TIE - LH	1	129.06	129.06	10.00	116.15	Replace	0	0	Check	?
One Time Key In	Main			ROD ASM-STRG LNKG OTR TIE - RH	1	129.06	129.06	10.00	116.15	Replace	0	0	Not Give	Xun
One Time Key In	Main			SHAFT ASM-FRT WHL DRV HALF - LH	1	1,635.80	1,635.80	10.00	1,472.22	Replace	0	0	Not Give	Xun
One Time Key In	Main			DOOR ASM-FRT SI - LH	1	2,338.76	2,338.76	10.00	2,104.88	Replace	1	0	Repair	Rp
One Time Key In	Main			STICKER STRIDES TAXI ( DOOR )	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	see ✓
One Time Key In	Main			MIRROR ASM-O/S RR VIEW - LH	1	478.40	478.40	10.00	430.56	Replace	0	0	Not Give	Xun
One Time Key In	Main			HOUSING-O/S RR VIEW MIR - LH	1	34.52	34.52	10.00	31.07	Replace	1	0	Repair	Rp
Total Spare Part Cost									16,157.71	Surveyor Total		3,245.39		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									16,157.71	Final Sur Total		3,245.39		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER ASM-FRT - RH	1	379.80	379.80	10.00	341.82	Replace	0	0	Not Give	Xun
One Time Key In	Main			FASCIA-FRT BPR	1	721.66	721.66	10.00	649.49	Replace	1	0	Repair	Ry
One Time Key In	Main			GRILLE-FRT BPR FASCIA LOWER	1	149.04	149.04	10.00	134.14	Replace	0	0	Not Give	Xun
One Time Key In	Main			FINISHER-FRT BPR LOWER - LH	1	20.38	20.38	10.00	18.34	Replace	0	0	Not Give	Xun
One Time Key In	Main			COVER-FRT FOG LP - LH	1	40.24	40.24	10.00	36.22	Replace	0	0	Not Give	Xun
One Time Key In	Main			FINISHER-FRT FOG LP CVR - LH	1	47.32	47.32	10.00	42.59	Replace	0	0	Not Give	Xun
One Time Key In	Main			BRACKET-FRT BPR FASCIA - LH	1	23.08	23.08	10.00	20.77	Replace	0	0	Check	?
One Time Key In	Main			FINISHER-FRT BPR - LH	1	98.80	98.80	10.00	88.92	Replace	0	0	Not Give	Xun
One Time Key In	Main			PANEL ASM-LEG CTHR	1	131.04	131.04	10.00	117.94	Replace	0	0	Not Give	Xun
One Time Key In	Main			BAR ASM-FRT BPR IMP	1	624.00	624.00	10.00	561.60	Replace	0	0	Not Give	Xun
One Time Key In	Main			COVER-F/CMPT ORNA	1	217.68	217.68	10.00	195.91	Replace	0	0	Not Give	Xun
One Time Key In	Main			BRACKET ASM-HDLP UPP - LH	1	22.56	22.56	10.00	20.30	Replace	0	0	Check	?
One Time Key In	Main			HEADLAMP ASM -LH	1	1,098.86	1,098.86	10.00	988.97	Replace	0	0	Check	?
One Time Key In	Main			HOOD ASM	1	2,407.28	2,407.28	10.00	2,166.55	Replace	1	2,166.5	Replace	66
One Time Key In	Main			HINGE ASM-HOOD - RH	1	54.80	54.80	10.00	49.32	Replace	0	0	Check	?
Total Spare Part Cost									16,157.71	Surveyor Total		3,245.39		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									16,157.71	Final Sur Total		3,245.39		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE ASM-HOOD - LH	1	54.80	54.80	10.00	49.32	Replace	0	0	Check	?
One Time Key In	Main			WEATHERSTRIP ASM-HOOD RR	1	20.80	20.80	10.00	18.72	Replace	0	0	Not Give	Fun
One Time Key In	Main			HOOD INSULATOR-F/CMPT	1	70.92	70.92	10.00	63.83	Replace	0	0	Not Give	Fun
One Time Key In	Main			PLUG-HOOD	2	0.42	0.84	10.00	0.76	Replace	0	0	Not Give	Fun
One Time Key In	Main			LATCH ASM-HOOD	1	80.70	80.70	10.00	72.63	Replace	0	0	Not Give	Fun
One Time Key In	Main			PANEL-BODY SI OTR FRT- LH	1	235.24	235.24	10.00	211.72	Replace	0	0	Not Give	Fun
One Time Key In	Main			FENDER ASM-FRT - LH	1	379.80	379.80	10.00	341.82	Replace	1	341.82	Replace	btv
One Time Key In	Main			BAR ASM-DA PNL UPR CR - LH	1	198.22	198.22	10.00	178.40	Replace	0	0	Check	?
Total Spare Part Cost									16,157.71	Surveyor Total		3,245.39		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									16,157.71	Final Sur Total		3,245.39		

Labour's Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	5,400.00	600	
Total:			5,400.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	428.00	220	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	230.00	0	
3	Main	TO RESPRAY FRONT HOOD	428.00	220	
Total:			3,290.00	940.00	



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY FRONT FENDER RH	428.00	0	
5	Main	TO RESPRAY FRONT FENDER LH	428.00	220	
6	Main	TO RESPRAY APRON PANEL LH	230.00	0	
7	Main	TO RESPRAY FRONT PILLAR LH	230.00	0	
8	Main	TO RESPRAY FRONT DOOR LH	428.00	220	
9	Main	TO RESPRAY VIEW MIRROR	230.00	60	
10	Main	TO RESPRAY RIM	230.00	0	
Total:			3,290.00	940.00	
Other Cost Detail					
S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
6	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
7	Main	TO REMOVE AND REFIX UNDERCARRIAGE	350.00	0	
8	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,630.00	410.00	
Summary					
			Estimator Assesment(\$)	Surveyor Assesment(\$)	
Total Spare Part Detail			16,157.71	3,245.39	
https://vacswb.smr.com.sg/Estimation.aspx					

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Labour Cost	5,400.00	600.00
Total Spray Painting	3,290.00	940.00
Other	1,630.00	410.00
Overall Total	26,477.71	5,195.39
Lump Sum Repair Option		
Lump Sum Total	0.00	5,195.39
Surveyor Approved Amount		5,195.39
No of Repair Days*	9	5
Remarks	-	PART BY PART REPAIR / BEFORE PAINT PHOTO / NEW PART AND OLD DAMAGE PART PHOTO .
Surveyor Name		Taufikh
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	04/03/2022	

**KK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 97495749  
WP 4/3/22 @ 1215pm  
r/p Resurvey before paint  
5 days  
taufikh@kkauto.com

(1/1)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/03/2022 10:59 (SGT)
Date of Accident	02/03/2022 13:07 (SGT)
Exact Location of Accident	Sembawang Rd, Singapore
Additional Location Information	SEMBAWANG ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1136E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

#### VEHICLE PARTICULARS

Manufacturer	MG
Model	MG5
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1

#### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

#### DRIVER

Name of Driver	YEO TIONG GUAN
NRIC No	SXXXX842D



Date Of Birth	14/02/1965
Occupation	Outdoor
Date Of Driving Pass	19/06/1987
Driving experience	34 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG SEMBAWANG ROAD TURNING RIGHT TOWARDS THOMSON AND THE TRAFFIC WAS IN MY FAVOUR. WHILST I WAS TURNING RIGHT, SUDDENLY I FELT AN IMPACT AT THE LEFT FRONT PORTION OF MY TAXI. A VEHICLE GBF8299Y FAILED TO STOP, AS SUCH COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8299Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	CHARANJIT SINGH

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency authority (such as the police) for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Sembawang Road

A - SHB 1136 E  
B - GBF 8299 Y

### Declaration

We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature Date & Time:

Driver's Signature if driver is not the policyholder: Vec 2-3-2022 Date & Time

Witnessed by Reporting Officer  
(Signature)