



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE			Ref: CC4/ASM22002071/Uea3q2 Date: 18/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMP 2854B	Veh. Inspected	SGZ 1619P	
Policy No.	GA500212	Coverage (\$)	0.00	
Claim No.	S2M03UG5	Excess (\$)	0.00	
Assign From		Assign Date	07/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MINI ONE 5DR	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WMWXU520X02N51034	Colour	GREEN	
Odometer	8415 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	PIRELLI	6 mm	
L/H Front Tyre	205/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	205/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2022	Inspection Date	07/03/2022	
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	