(08/11/13) wef

ASS. REC. BY: Marcus

REF: CCG/AIG22002072/Upa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJK5879Y

at Workshop m/s Tandem

of

Insured: GBH 4717Z

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $40k.

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: 3 days Res.: **Yes** or **No**

Lum Sum: 20 % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS c 30pm

Vehicle: **IN / OUT**

Date: Person Contacted: LTA 20099

Veh No: SJK5879Y Yr Regn: 28/10/08

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or (A)

Make: Toyota corolla AHJ c.c 1598

Colour Silver A/C: **Insured / Std / NI / NA**

Sp.Reading 324534 T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: MR0E3ZEE10G121769

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Falken

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	3/3/22	D.O.I.	7/3/22

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or Rear

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time Action / Instruction Dip TK.

No BI COE until 27-10-2028

16/3/22 4/S $1500 informed William

Date/Time, File Pass to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS, ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL