

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22002105/Rvy3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	24/03/2022	
	ATTN: TEO KITTY			Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 7273S	Veh. Inspected		SMW 2579J	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03UZG	Excess (\$)		0.00	
	Assign From	TEO KITTY	Assign Date		07/03/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	AUDI A7 SB 3.0 TFSI QU	c.c		2995	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	WAUZZZ4G4EN114843	Colour		BLACK	
	Odometer	142836 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	275/30 R20	MICHELIN		6 mm	
	L/H Front Tyre	275/30 R20	MICHELIN		6 mm	
	R/H Rear Tyre	275/30 R20	MICHELIN		6 mm	
	L/H Rear Tyre	275/30 R20	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
5.	General Information					
	Accident Date	04/03/2022	Inspect Date /	Time	15/03/2022 ( 12:24 PM )	
	Survey held at HIAP LEK AUTOMOBILE TRADING					
	160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	c. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22002105/Rvy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**