

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

7-Mar-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6479C

1 pc	o/s tail lamp @\$421.00	\$	421.00
2 pcs	n/s & o/s reflector @\$350.00	\$	700.00
1 pc	Boot lid	\$	1,119.00
1 pc	Boot lid lock	\$	99.00
1 pc	Bootlid striker	\$	21.00
1 pc	Bootlid emblem	\$	27.00
1 pc	Bootlid CRDi	\$	29.00
1 pc	Boot lid rubber weatherstrip	\$	96.00
1 pc	Boot lid lower garnish	\$	290.00
2 pcs	Bootlid hinges @ \$66.00	\$	132.00
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00
1 pc	Bootlid inner trim	\$	190.00
1 pc	End panel	\$	250.00
1 pc	End panel inner garnish	\$	74.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00
		\$	5,461.00
		Less 10%	\$ 546.10
		\$	4,914.90

7-Mar-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6479 C

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	End panel inner garnish clips	\$	30.00
1 set	Bootlid inner trim clips	\$	52.00
1 set	Bootlid lower garnish clips	\$	60.00
1 set	Bootlid stickers	\$	100.00
1 set	Reverse sensor	\$	280.00
1 pc	Rear bumper top protector	\$	80.00
1 pc	Rear no. plate with casing	\$	50.00
1 pc	Sealant	\$	50.00
	Sundry	\$	50.00
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00
	Towing fee	\$	50.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel,. Including knock-out, straighten, repair, reshape and adjust of the rear panel		\$1,000.00
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper,end panel, bootfloor	\$	1,000.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00
		<u>\$</u>	<u>8,184.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

[Handwritten signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

07 MAR 2022


[Handwritten signature]

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SHC 6479C

B: GBD 4788Y





**SINGAPORE
POLICE FORCE**



T/20220304/2128

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

1 of 3
Report No. T/20220304/2128

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/03/2022 20:18		Vide Report No.:		Station Diary No.: 24	
Informant's Particulars					
Name of Informant: TAN TECK SAN			Address: APT BLK 632B SENJA ROAD #04-109 SINGAPORE 672632		
ID Type / ID No.: NRIC NO / S1528952Z			Contact No.: Home/Office: Mobile: 97891070		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 18/10/1962	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 04/03/2022 15:35	Type of Location: Straight Road
Location: WHITLEY ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD4208Y	Lorry					0
SHC6479C	Car					2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20220304/2128

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

2 of 3

Report No. T/20220304/2128

CONTINUATION OF REPORT

Driver			
Name	DAI JISONG	ID No.	G2980402N
Related Vehicle	GBD4208Y (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN TECK SAN	ID No.	S1528952Z
Related Vehicle	SHC6479C (Car)	Contact No.	97891070
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	04/03/2022	Date Discharge	04/03/2022
No. of Days granted Medical Leave	07	Degree of Injury	NIL

Brief Details.

On the above mentioned date and time I was driving my taxi SHC6479C on the left-most lane along Whitley road heading towards PIE-Jurong. I had a female passenger with her daughter seated at the back passenger seats. I was in a queue behind a line of vehicles, driving along to turn into the slip road into PIE. While my taxi was in motion suddenly I felt an impact from the rear of my taxi. At the moment of the impact my head hit the driver's side door. After the impact I checked on my passengers and they told me that they have no immediate injuries. I myself felt pain at the back of my right shoulder and at the side of my head. Thereafter I went out of my taxi to make a check and discovered a lorry GBD4208Y had collided into the rear of my taxi. I made a check on the driver of the said lorry and was told by him that he had no immediate injuries. No police and no ambulance was called to the accident scene. Then I exchanged particulars with the said lorry driver and left the scene to send my passengers to their destination. After that I went to seek medical attention at clinic and was discharged the same day with seven days medical leave.


INSURER ENQUIRY

Find insurer

Vehicle reg. no.

GBD4208Y

Date of Accident

04/03/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance China Taiping Insurance (Sing...

Period of Insurance 14/10/2021 - 13/10/2022

Requested By NG BOON KAI (PREMIER AUTO...

Requested Date 07/03/2022 13:39

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Enquire Transaction History

Transaction History Details

Log Date/Time:	19 Mar 2015 / 10:32:30	Receipt No.:	AACCK001-AX239-150319-000024
Asset Type:	Vehicle	Transaction Amount:	\$65,578.00
Asset ID:	SHC6479C	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150319103230353638		

Vehicle No.:	SHC6479C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	19 Mar 2015
Original Registration Date:	19 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis-No.:	KNAGM414MF5593368
Engine No.:	D4FDEH313386
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,318.00
Minimum PARF Benefit:	\$8,607.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	19 Mar 2015 10:32:30
COE No.:	2015031901002284E
COE Expiry Date:	18 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	18 Mar 2023