

CT 1

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA2879T

Make : HYUNDAI

Model : IONIQ(G2)

Date: 03/03/22

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			<i>Ry</i> \$459.40
10	REAR BUMPER CLIPS			<i>all</i> \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			<i>?</i> \$451.25
1	ANTENNA SMARTKEY			<i>x</i> \$40.50
1	REAR BUMPER FOG LAMP			<i>x</i> \$201.50
	SUB TOTAL			\$1,174.65
	LESS 20%			\$234.93
	DISCOUNTED TOTAL			\$939.72
	REAR FENDER ADVERTISEMENT LOGO RH			<i>net</i> \$100.00
	REAR FENDER ADVERTISEMENT LOGO LH			<i>net</i> \$100.00
	REAR BUMPER REVERSE SENSOR			<i>?</i> \$180.00
				\$380.00
	Labour Charge			
	PANEL BEATING			<i>35</i> \$400.00
	SPRAY PAINTING CHARGE			<i>250</i> \$300.00
	CHECK ALL LIGHTING			<i>x</i> \$60.00
	REMOVE/REFIX REVERSE SENSOR			<i>30</i> \$80.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$2,159.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfer 97495749
wp 3/3/22 @ 5pm
2 days
Resurvey new parts
Tanfer@khantam

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.03.2022 08:56

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4180221

JC NO305507219

STOMER

REGN NO.:

SHA2879T

MILEAGE

/MS COMFORT TRANSPORTATION PTE LTD

STOMER NO. 7010045

MAKE :

HYUNDAI

FUEL

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

MODEL

IONIQ(G3)

02.03.2022 15:25

(R) 65508755 (O)

YR OF MANU.

22.10.2019

TARGET DATE

(P)

CHASSIS CODE

KMHC851CVLU186567

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 02.03.2022

ATURE: 3P 02.03.2022

/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

:

o.:

e No.: SHA2879T

YY

Vehicle No.:

SHA2879T

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard