



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22002168/Avy3e2 Date: 04/07/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLS 6103E	Veh. Inspected	SMR 1469B
Policy No.		Coverage (\$)	0.00
Claim No.	C10014167/EE	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	08/03/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK33427119	Colour	SILVER
Odometer	154229 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	FARROAD	6 mm
L/H Front Tyre	195/55 R15	FARROAD	6 mm
R/H Rear Tyre	195/55 R15	FARROAD	6 mm
L/H Rear Tyre	195/55 R15	FARROAD	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/03/2022	Inspection Date	07/03/2022
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	