

Ass. Rec. By:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMT971M Yr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw X1 c.c 1499

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 33790 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJG12060EN52573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 09/03/22

Survey held at Ventures

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front m/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AXA</u>
	<u>MV: 130K</u>
	<u>PV: 59.1K</u>
	<u>Nett: 70.9K</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

_____ \$ + RS _____ \$

Photos _____

Others _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/03/2022 13:54 (SGT)
Date of Accident	02/03/2022 13:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNC OF FARRER RD & DUNEARN RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMT971M
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEE CHEE MENG HUBERT
NRIC No	S7535396J
Email Address	a6679b@gmail.com
Mobile Phone No	(Phone) +65-91136456
Alternative Phone No	+65-91136456

VEHICLE PARTICULARS

Manufacturer	BMW
Model	X1
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00068792100
Cover Note Number	-

DRIVER

Name of Driver	PUA YEE KWAN
NRIC No	S7703653I

Date Of Birth	27/01/1977
Occupation	Indoor
Date Of Driving Pass	06/05/2003
Driving experience	18 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-83892701
Alt. Phone Number	-
Email Address	a6679b@gmail.com
Address	16 SHELFORD ROAD
Address complement	#02-10
Postcode	288383
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	SOPHIE LEE
Gender	Female

PASSENGER 2

Name	SARAH LEE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE ATTACHED STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA8520M
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	THEN THIAM SHIN
NRIC No	S0152194B
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time


 Driver's Signature (if driver is not the policyholder) / Date & Time

 03/03/22
 Witnessed by Reporting Centre Personnel

Sketch Plan



A - SMT 971M
 B - SHA 8520M

Describe Circumstance of the Accident


Describe Circumstances of the Accident


On 2/3/2022 at about 1310 hour, I was driving SM7971M along Farrer Road towards ~~then to~~ Dharmapala Road with 2 passengers onboard. I stopped at the junction of Farrer Road and Bukit Timah Road and was on the extreme right lane of 4 lane (only right turn) due to red light. When the lights turned green, I proceeded to move forward to go straight. Just as I passed the traffic light where I was, a taxi suddenly cut in front of my car, coming from my left. I made an immediate brake in the middle of the road junction of Farrer Road and Bukit Timah Road. The taxi continued to swerve into my lane and caused ~~an~~ an impact on the front left bumper and vent. My car was stopped in the middle of the cross junction of Farrer Road and Bukit Timah Road. Due to the traffic soon coming from Bukit Timah, I had to drive to side of the road for 2 young passengers' safety. When I came out of the car, I realised a taxi SHAS 8122M that ^{suddenly} swerved into my lane, collided onto my vehicle and caused damage. Taxi driver apologised for his oversight ~~to~~ and we exchanged particulars and left the scene.

error and ^

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time


 Driver's Signature (If driver is not the policyholder) / Date & Time

 03/03/22
 Witnessed by Reporting Centre Personnel

VENTURES AUTO PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 202143430K

VEHICLE REPAIR ESTIMATE

Make/ Model : BMW X1 Date: 07.03.2022

Chassis No : WBAJG12060EN52573 Vehicle No: SMT971M

Date/Time of Accide: 02.03.2020/1310 Original Reg : 26.04.2019

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE	FINAL PRICE \$
1	FRONT BUMPER <i>Dechud</i>	1	798.50	798.50
2	FRONT BUMPER RETAINER LH ?	1	86.30	86.30
3	FRONT BUMPER LOWER <i>at</i>	1	453.90	453.90
4	FRONT BUMPER FOGLAMP LH ?	1	325.60	325.60
5	FRONT BUMPER SENSOR <i>1 piece chud</i>	3	298.70	896.10
6	FRONT BUMPER SENSOR HOLDER <i>new</i>	1	158.90	158.90
7	FRONT BUMPER AIRVENT LH ?	1	276.55	276.55
8	FRONT BUMPER AIRVENT GARNISH LH <i>at</i>	1	135.60	135.60
9	FRONT BUMPER TOP SUPPORT BEAM <i>at</i>	1	217.85	217.85
10	FRONT BUMPER SPONGE ?	1	225.60	225.60
11	FRONT BUMPER CORNER BRACKET <i>new</i>	1	19.80	19.80
12	FRONT BUMPER REINFORCEMENT <i>new</i>	1	498.70	498.70
13	FRONT OIL COOLER <i>new</i>	1	1,258.90	1,258.90
14	FRONT BUMPER SIDE AIR VENT <i>new</i>	1	156.20	156.20
15	FRONT LOWER BEAM ABSORB BRACKET <i>new</i>	1	168.50	168.50
16	FRONT FENDER LH <i>new</i>	1	685.90	685.90
17	FRONT FENDER INNER COWLING LH <i>new</i>	1	175.90	175.90
18	FRONT FENDER ARCH GARNISH LH <i>at</i>	1	235.70	235.70
19	FRONT BUMPER UNDER COVER <i>new</i>	1	345.60	345.60
20	FRONT HEADLAMP HID LH <i>at ?</i>	1	2,870.85	2,870.85
21	FRONT HEADLAMP LOWER BRACKET LH <i>at</i>	1	275.80	275.80
22	FRONT MIRROR ASSY LH <i>new</i>	1	1,782.50	1,782.50
23	Front rim LH <i>at</i>	1	1,548.90	1,548.90
24	Front Lower Arm LH ?	1	389.70	389.70
25	Front trailing Arm LH	1	392.60	392.60
26	Front Knuckle Arm LH <i>new</i>	1	498.50	498.50
27	Front Wheel hub Bearing LH	1	502.90	502.90
28	Front ABSORBER LH	1	523.80	523.80
29	Front ABSORBER MOUNTING LH ?	1	98.50	98.50
30	Front STABILIZER LINK	1	125.60	125.60
31	FRONT STABILIZER BAR BUSH <i>at</i>	1	48.50	48.50
32	FRONT DOOR LH <i>new</i>	1	1,358.90	1,358.90
33	FRONT DOOR OUTER GARNISH LH	1	345.60	345.60
34	Sideskirt LH	1	798.20	798.20
Total List Price Cost				\$ 17,882.75
PARTS DISCOUNT 5%				\$ 16,988.61

Handwritten notes and markings on the right side of the table, including checkmarks, question marks, and the number '28870'.

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
2	SIDESKIRT CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
3	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
4	FRONT BUMPER LOWER COVER CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
5	HEADLAMP CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
6	FRONT DOOR OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
7	FRONT FENDER ARCH GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	30.00
Total Special Nett Items				\$ 210.00
Labour Works/ Panel Beating Related Works				
Job Scope				Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS				\$ 1,800.00 <i>300</i>
Spray Painting				
Job Scope				Quotation
TO RESPRAY AFFECTED AREAS				\$ 1,800.00 <i>250</i>
Others Cost (Accident Repair Related Expenses)				
Job Scope				Quotation
TO TUFFCOAT AFFECTED AREA				\$ 180.00 <i>+</i>
TO REMOVE/ REFIT WIRING CHECKS ON FRONT HEADLAMP/ FOCUSSING				\$ 120.00 <i>30</i>
TO REMOVE/ REFIT DOOR PARTS AND MECHANISM				\$ 300.00 <i>+</i>
TO REMOVE AND REPLACE FRONT UNDERCARRIAGE				\$ 250.00 <i>+</i>
TO REMOVE/REPLACE FRONT SENSOR AND DISTANCE SETTLING				\$ 120.00 <i>50</i>
TO PERFORM COMPUTERISE WHEEL ALIGNEMNT (BEFORE & AFTER)				\$ 120.00 <i>80</i>
Total Others Cost				\$ 1,090.00
GRAND TOTAL				\$ 21,888.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian L
 h/s 09/03/22.
 03 Aug

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 396J

Vehicle Details

Vehicle No.: SMT971M
Vehicle to be Exported: No
Intended Deregistration Date: 09 Mar 2022
Vehicle Make: B.M.W.
Vehicle Model: X1 SDRIVE18I LED NAV
Primary Colour: Grey
Manufacturing Year: 2019
Engine No.: 32785584B38A15A
Chassis No.: WBAJG12060EN52573
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$36,905.00
Original Registration Date: 26 Apr 2019
First Registration Date: 26 Apr 2019
Transfer Count: 2
Actual ARF Paid: \$43,667.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Apr 2029
PARF Rebate Amount: \$32,750.00

Intended COE Rebate Details

COE Expiry Date: 25 Apr 2029
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
QP Paid: \$37,620.00
COE Rebate Amount: \$26,344.00
Total Rebate Amount: \$59,094.00

The information contained herein is correct as at 09 Mar 2022

OK

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Wish 1.8X A



Low Usage, Cheapest In The Market! Good For Short Term Usage, Superb Condition! Direct Owner

ABWIN banner with 'Visit Our Profile' button and images of cars.

Sort by Date Posted 20 results/page

5 vehicles



bmw x1

Any Category

Advanced Search

Table listing 5 BMW X1 sDrive18i vehicles with columns for Make, Model, Price, Depreciation, Reg Date, Eng Cap, Mileage, Veh Type, and Status. Includes descriptions and agent information for each listing.

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Compare