

Vehicle Damage Assessment Report for [GBL4754U]

Estimate Created: 25/03/2022 04:17 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 15/12/2022 12:25 by LKK_assignments (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	India International Insurance	Claim Number	MFL2021D0004384
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Nissan	Model	NV350
Engine Type			
License Plate Number	GBL4754U	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$400.00 WITH 1 DAYS	Insurlogic 5 (15/12/2022 12:24)
---	---------------------------------

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING ,REMOVAL AND REPLACING PARTS	RnR	200.00	0.00 %	200.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR BUMPER	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO SPRAY PAINT AFFECTED AREA	Full spray	200.00	0.00 %	200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 200.00

Paint Labor Subtotal 200.00

Labor Subtotal 400.00

Summary

Repair Cost 400.00

Discount(0 %) (0.00)

400.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 400.00