



Your Ref: S1M03N55

Date: 11th Apr 2022

Our Ref: CS3/ASM21012137/Gvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Teo Kitty

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBF 1339L

INSURED VEHICLE: SHC 8078M

ACCIDENT DATE: 27/11/2021

We thank you for your instruction on 08/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBF 1339L from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBF 1339L and SHC 8078M.
- c) Final Repair Bill of GBF 1339L from M/s Speedwerkz Pte Ltd.
- d) Colour damaged vehicle photographs of GBF 1339L.

Pre-Repair Inspection Date : 30/11/2021 at M/s Speedwerkz Pte Ltd, 13 Kaki Bukit Road 4, #01-20, Bartley Biz Centre, Singapore 417807.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF 1339L
Make & Model	: Nissan NV200 1.5 MT ABS / Airbag 6
Year of Registration	: 2016
Chassis Number	: VSKYBAM20Z0126998
Engine Capacity	: 1461 cc

2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.