

Figure B-2: Incident Schematic




Figure 1A: Schematic Diagram Pt. 1




Figure B-4: Incident Schematic




Figure 1B: Schematic Diagram Pt. 2






Figure 2A: Front and Left Side of MID 33920






Figure C-4: Rear Side of MID 33920



Figure 2B: Right Side and Rear of MID 33920



Figure C-6: Left-hand tyre of MID 33920



Figure 2C: Close up of Damages SECURITY CLASSIFICATION \ SENSITIVITY CLASSIFICATION





Figure 2D: Front and Left Side of SMK 5363H





Figure 2E: Right and Rear View of SMK 5363H

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

TATEMENT OF	256 UM KAT UK	a , LAHAN				ALIASE	3		5
IRIC NO	063 F	AGE 90	20	2	0	MALE/F	EMALE	MACE	
MPLOYMENT	N& P	DRIVING	i de la companya de l	clas	5 3	NATION	ALITY	gru6,09	0.8-64-1
MALECT	-	LANGUA	GE	Bulada	н	TEL NO			
MDDRESS		SPLIKEN		GENVON	0	7/11/20/20			
NTERPRETED BY		RANK		TIME		DATE		SIGN	
RECORDED BY	BE NOW YOU TE	RANK	217	TIME	2030	DATE	010312	SIGN	70.76
	MN UM WIS DIN	was h	DetailAl	rim	THU KAN	G 1200	D ON	THE W	e7 70
MY VEHIC F WAS T PERMISSI	CIG COMMODER Fro LATE book 87 GEWE F	2 . JUST L - IT MAS WHIT	BEI WAS 1 PO AND	PORE THE	LORT O	HUSED U	I HEAR I WAS ALTIEN	DEFINA	HT' FROM
HIT THE THE NEPE.	SIDE OF THE	TURNED YULUM P. WE	N VI	L LEF		HELY MELY	1 BRA	LATE E	NO POT

Figure 3A: Driver's Statement

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

	9		E ARMED FORC			
STATEMENT OF	COL PONTANONAN			ALIASES	-	
HIC NO	62.GF	AGE	25	MALEFEMALE	1000	
EMPLOYMENT	NA	DRIVING	SAFITHIN/DIOGULAT	NATIONALITY	SINGAPORFAMI	
DIALECT	2	LANGUAGE	ENWASH PRACAY	TEL NO	girlani - t - sa - t	
ADDRESS		SPOKEN	4998881/M0/9/	Min-Street		
INTERPRETED BY		RANK	TIME	DATE	SIGN	
RECORDED BY		RANK	TIME	DATE	SIGN	
ALTERNATION OF THE PARTY OF THE	phil the vehicle w	agn't going		upot . So repetit	edly ask to overve	-
to the night driver sweet bourseing. The bourseing to the but of the bour later	the vehicle we that the vehicle has	eson't going. So the let will be right to a moving to	back to the P nicle mountal the ying to avoid the vehicle and I the direction of t civilian vehicle	e but stop to 900 him and 900 him and he vehicles or	ne his stop the he kenkle kept hig to counter I have opp lane.	itg

Figure 3B: TOG's statement

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

olice Station (hoa Chu Kan 0 Choa Chu K	g N.P.C ang Stre	eet 52 #01-02					Report N	lo. T/20220301/209
0 Choa Chu K	ang Stre	et 52 #01-02						
INGAPORE 6	89286							
el No: 1800-7	659999							
Date/Time Re			104- 0				Sta	tion Diary No.:
01/03/2022 22	2:04	В.	Vide Report No.:					l Diary 140
Informant's P		rs		-	distant.			
Name of Infor			Addres	s:				
ID Type / ID N NRIC NO /	lo.: 063F		Contact No.: Home/Office: Mobile:					
Nationality:	-		Email:			ITIODITO.		
SINGAPORE			Torri	Clafe				
	ige:	Date of Birth: 06/12/2001	Type o	of Informan	E.			
Race:			Langu	age;		Institutio	on / Sch	nool Name:
Occupation:			Driving Licence Information:					
Occupation:		Driving	Licence Ir	nformation:	-			
		ces personnel	Class:		nformation:	Date of	Expiry:	
	mation o	of the Accident n-Injury vernment Vehic	Class		Date/Tin Acciden	ne of	11	
General Infor	mation o	of the Accident	Class	Drink Drive:	Date/Tin Acciden	ne of	11	Type of Location
General Infor	mation o	of the Accident n-Injury vernment Vehic	Class	Drink Drive:	Date/Tin Acciden	ne of	11	Type of Location
General Information Type of Accident: Location: LIM CHU KA	mation o	of the Accident n-Injury vernment Vehic	Class	Drink Drive: No	Date/Tin Acciden	ne of	1	Type of Location Straight Road
General Information Type of Accident: Location: LIM CHU KA Weather:	mation o	of the Accident n-Injury vernment Vehic	Class	Drink Drive:	Date/Tin Acciden	ne of	1	Type of Location
General Information Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow:	mation o	of the Accident n-Injury vernment Vehic	Class:	Drink Drive: No Surface:	Date/Tin Acciden	ne of	Road	Type of Location Straight Road Speed Limit:
General Infor Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow: Two Way	Mation of Roa	of the Accident n-Injury vernment Vehic	Class:	Drink Drive: No Surface:	Date/Tin Acciden	ne of	Road Traffic Moder	Type of Location Straight Road Speed Limit: : Volume: rate
General Information Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow:	Mation of Roa	of the Accident n-Injury vernment Vehic	Class:	Drink Drive: No Surface:	Date/Tin Acciden	ne of	Road : Traffic Moder	Type of Location Straight Road Speed Limit:
General Information Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow: Two Way Type of Collis	NG ROA	of the Accident n-Injury vernment Vehic	Class:	Drink Drive: No Surface:	Date/Tin Acciden	ne of	Road Traffic Moder Anyon ambul	Type of Location Straight Road Speed Limit: Volume: rate ne conveyed by
General Infor Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow: Two Way	NG ROA	of the Accident n-Injury vernment Vehic	Road Wet Traffic Not C	Drink Drive: No Surface:	Date/Tin Acciden	ne of t: 022 16:30	Road Traffic Moder Anyon ambul	Type of Location Straight Road Speed Limit: Volume: rate ne conveyed by
General Information Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow: Two Way Type of Collis	NG ROA	of the Accident n-Injury vernment Vehic	Road Wet Traffic Not C	Drink Drive: No Surface: Control:	Date/Tin Acciden 01/03/20	ne of t: 022 16:30	Road : Traffic Moder Anyor ambul No	Speed Limit: Volume: rate ne conveyed by lance:
General Information Type of Accident: Location: LIM CHU KA Weather: Raining Traffic Flow: Two Way Type of Collis Details of Vel Vehicle No.	NG ROA	of the Accident n-Injury vernment Vehic	Road Wet Traffic Not C	Drink Drive: No Surface: Control:	Date/Tin Acciden 01/03/20	ne of t: 022 16:30 Co. Slig Da.	Road Traffic Moder Anyon ambul No	Speed Limit: Volume: rate ne conveyed by lance: No of Passeng 2

Figure 4A: Police Report Pt. 1




Figure 4B: Police Report Pt. 2




Figure 4C: Police Report Pt. 3