

AXA Insurance Pte Ltd

## Assessments

### General Details

Involving 2019 TOYOTA FORTUNER 2.7 (SMK5363H)  
Date of Loss 01/03/2022  
Time of Loss 04:30 PM  
Loss Description 33920MID (Tp) C/W SMK5363H (INSD)  
Comment 10 working days

### Vehicle Details

Vehicle Registration# SMK5363H  
Registration Province  
Mileage 43952.00  
Manufacturing Year 2019  
Purchase date 15/04/2019  
Registration date 2  
Age of vehicle

|                 | Policy Information | Assessment Information |
|-----------------|--------------------|------------------------|
| Make            | TOYOTA             | TOYOTA                 |
| Model           | FORTUNER 2.7       | FORTUNER 2.7           |
| Type            |                    |                        |
| Type of paint   |                    |                        |
| Chassis No      | MHFGX3GS100420163  |                        |
| Engine No       | 2TRA616605         |                        |
| Engine Capacity |                    |                        |
| Sum Insured     | 0.00               | 0                      |
| Market Value    | 0.00               | 0                      |

Workshop Details

|                         |      |
|-------------------------|------|
| Total Rebate Amount     | 0.00 |
| Net Loss Amount         | 0.00 |
| Assigned Workshop       |      |
| Days of work completion | 10   |

Assessment Summary

| Category    | Revised Amount |
|-------------|----------------|
| Labour      | 8,854.76       |
| Spare Parts | 9,853.52       |
| Excess      | -500.00        |

|                               |           |
|-------------------------------|-----------|
| Settlement %                  | 100.0     |
| Amount Non-standard Deduction | 0.00      |
| Final Claim Amount            | 18,208.28 |

Detailed Assessment

|                                             |          |
|---------------------------------------------|----------|
| Inspection Date                             | 20220302 |
| Assessment Details                          |          |
| Total Loss                                  | false    |
| Towing Charges                              | 0.00     |
| Voluntary Excess                            | 0.00     |
| Compulsary Excess                           | 500.00   |
| Young/ Inexperienced/ Unnamed Driver Excess | 0.00     |
| Other Excess                                | 0.00     |

Condition of vehicle at time of survey

|                        |      |
|------------------------|------|
| General condition      | Good |
| Steering (Serviceable) | true |

Footbrake (Serviceable) true  
Handbrake (Serviceable) true  
Engine Modification false  
Pre-accident condition

**Tyre condition**

Age of tyres 265/60/18  
Front Tyre Size 265/60/18  
Rear Tyre Size 6  
Front left side 6  
Rear left side 6  
Front right side 6  
Rear right side 6  
Spare wheel

**Parts**

| No. | Quantity | Part Name          | Condition | Dep/Batt% | Discount % | Salvage % | Adjusted Amount | Supplementary Parts | Action  | Comment |
|-----|----------|--------------------|-----------|-----------|------------|-----------|-----------------|---------------------|---------|---------|
| 1   | 1.00     | TOTAL PARTS AMOUNT |           | 0         | 0          | 0         | 9853.52         | Yes                 | Approve |         |

Labour

| No. | Description         | Adjusted Labour Amount | Adjusted Paint Amount | Action  | Comment |
|-----|---------------------|------------------------|-----------------------|---------|---------|
| 1   | TOTAL LABOUR AMOUNT | 8854.76                | 0                     | Approve |         |
| 1   | 10 working days     |                        |                       |         |         |

Miscellaneous

| No. | Name | Adjusted Amount | Action | Comment |
|-----|------|-----------------|--------|---------|
|-----|------|-----------------|--------|---------|

Paint Labour/Material Ratio

Paint Labour Ratio20.0  
Paint Material Ratio80.0  
Cash Lossfalse