

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 20051400L

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Not Authorized
11 Rm @ 2450h
Pruning After Paint
2 days

Estimate : TP22/010

Date : 04/04/2022
Vehicle Num. : SKU 6228E
Make/Model : TOYOTA ALTIS-2015
Chassis/Eng# : MR053REH104537783/1ZRY203038
Accident Date : 06/03/2022
Claim No. :
Reference : LYB/SKU6228E/AXA/tp/sl
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER	531.10	
3.	1	FRONT BUMPER RETAINER/LH	2816.50	
4.	1	FRONT HEADLAMP/LH		
5.	1	FRONT GRILLE		
	1	FRONT FENDER EMBLEM		

List TotalS\$:
25.00% Discount S\$:

for no plate

LABOUR :
TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION
TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS
TO CHECK COMPUTERISED WHEEL ALIGNMENT
TO REPAIR, PANELBEAT, ALIGN ON LEFT FRT FENDER & BONNET
AND LABOUR TO REPALCE ABOVE PARTS
TO PUTTY,PRIMER & SPRAY PAINT ON LEFT FRT FENDER, FRT
BUMPER & AFFECTED FRT BONNET USING 2K PEARLESCENT PAINT


Labour Total S\$:

<i>Bu</i>	563.00	<i>—</i>
<i>Dii</i>	90.40	<i>—</i>
<i>cm</i>	3,180.20	<i>—</i>
<i>su</i>	680.70	<i>X</i>
<i>nn</i>	31.90	<i>X</i>
	4,546.20	
	1,136.55	
	3,409.65	

	55.00	<i>201</i>
<i>nn</i>	120.00	<i>X</i>
<i>nn</i>	120.00	<i>X</i>
	800.00	<i>200</i>
	900.00	<i>2501</i>
	1,995.00	

E. & O.E.

Total S\$: 5,404.65



for LIM YEW BOO SPRAY PAINT CO.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: