(08/11/13)
ASS. REC. BY:

REF: CS6/AIS22002211/Kty3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. 2022 22003876SL

Sum Insured: Excess: 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 62000

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: SLJ 1541D Yr Regn: 29/11/2016

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Honda HRV 1.5 c.c 1496

Colour A/C: **Insured / Std / NI / NA**

Sp.Reading T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JHMRU1830GX * 201388

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: **F:**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	mm	R/Bal.	mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	

Survey held at

Des. of Damages : **Frt / Rear / O/S / N/S / U/C / Rooftop** or front

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	lump sum $6100, 6days
	red: 3090.60;33%

Date/Time, File **Pass** to?

1)

Date/Time, File **Return** to?

2)

☐ : **Preli. Report**

☐ : **Final Report**

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: ___S + RS, ___SI

Photos

Others

TOTAL