



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9887 4031  
 Email: yeeautopteitd@gmail.com  
 Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

Estimate No: ES2100144  
 Date: 08 Mar 2022

ATTN: Motor Claim Department

*Not within  
 1/1m @ 4300h  
 Penny after pain  
 4 days*

Policy No:  
 Veh Reg No: YN9523D  
 Make/Model: UD TRUCKS  
 PKC8ELN5EP  
 Chassis No: PKC8E30558  
 Engine No: GH7208401  
 Reg. Date: 01/10/2015

Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 21/02/2022  
 TP Veh Reg No: XE4335Y

### Estimate Repair Cost to Vehicle No : YN9523D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>Spare Parts</b>				
1 HORIZONTAL SOLID WOODEN BAR	500.00	3 PCS	CM 1,500.00	✓
2 REAR CARGO SIDE GATE (WOODEN) - LH	850.00	1 PC	CM 850.00	✓
3 REAR CARGO SIDE WOODEN BRACKET - LH	100.00	2 PCS	CM 200.00	✓
4 REAR CARGO SIDE WOODEN RAILING (ONG LYE PING) - LH	800.00	1 PC	CM 800.00	✓
5 REAR CARGO SIDE WOODEN RAILING (ONG LYE PING) BRACKET - LH	30.00	4 PCS	CM 120.00	✓
6 REAR WHEEL TOP COVER - LH	250.00	1 PC	CM 250.00	X
			3,880.00	3,880.00
<b>Labour</b>				
7 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	600
8 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	450
9 TO SUPPLY & ADJUST THE CARGO ALIGNMENT.	500.00	1 JOB	500.00	350
			2,100.00	2,100.00
			Total	SS 5,980.00
			Add GST @ 7%	418.60
			Total Amount Payable	SS 6,398.60

TOTAL: SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED NINETY EIGHT AND CENTS SIXTY ONLY

For Yee Auto Pte Ltd

10%

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

AUTHORISED SIGNATURE