

ASS. REC. BY: Taufik REF: CS/CT122062233/TVYS.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: GBF 3781D
 Policy No. DMCVSNW00116792100
 Claims No. SNM22D201285/C03/CSC
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 414K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: FBS3489E Yr Regn: 2021 / March
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda ADV 150 c.c. 149
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH1KF6110MK 034512
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: N/S / Rim / STD A/Rim or _____
 Tyre Size: F: 110/80R14
 R: 130/70R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Federal
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 19/2/2022 D.O.I. 9/3/22
 Survey held at New Union Company
 Des. of Damages: FT / Rear / O/S / N/S / U/C / Rooftop or
FT N/S, FT, O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/5/22	Taufikh informed LS \$2050 (red 2724, 57%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 17/5/22-typist

Report Format: Merimen

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

P

Email: numotor@singnet.com

Quote Date: 10-03-2022

cut ✓
cut ✓
x
x
x
x
x
cut ✓
x
cut —
cut ✓
cut ✓
cut —
bt —
x
cut —
cut —
cut —
x
x
x
60 ?
x
x
x
x
x
cut —
x
x

Continue next pg

New Union Company

GST Reg No. M90370043N

9004 Tampines Street 93 #01-106
Singapore 528838

P: 67849488
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern

Phone:

Quotation No. #:10_03_2022_I

Address: -

Fax:

Quote Date: 10-03-2022

Email:

Quotation For: Bike Repair - FBS3489E

Item #	Description	Qty	Unit Price	Discount	Price
31	Exhaust Cover Protector, Rear	1	\$ 97.00		\$ 97.00
32	Exhaust Cover Protector, Side	1	89.00		\$ 89.00
33	Exhaust Cover Protector, Front	1	78.00		\$ 78.00
34	Exhaust Gasket	1	65.00		\$ 65.00
35	Towing	1	65.00		\$ 65.00
36	Chassis - Repair	1	350.00		\$ 350.00
37	Labour Charge	1	350.00		\$ 350.00
38					\$ -
39					\$ -
40					\$ -
41					\$ -
42					\$ -
43					\$ -
44					\$ -
45					\$ -
46					\$ -
47					\$ -
48					\$ -
49					\$ -
50					\$ -
51					\$ -

int-
b/t ✓
cut-
X
50? towing
use app.
K
200

Sub-Total b/f GST	\$ 4,494.00
Tax Rate	7.00%
GST	314.58
Other	
Deposit Received	
Grand Total with GST	\$ 4,808.58

Customer Signature

Make all checks payable to New Union Company.

Taufik 97445749
WP' 9/3/22 @ 520pm
L/S Resurvey of kkn repair
taufik@lkkauto.com.
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: