

ASS. REC. BY: Taufik

REF: CS/CT122062233/TVYS.

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 414K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: FBS3489E Yr Regn: 2021 / March
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda ADV 150 c.c. 149
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH1KFB110MK 034512.
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: N/S / S/Rim / STD A/Rim or
Tyre Size: F: 110/80R14
R: 130/70R14
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Federal
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. _____ D.O.I. 9/3/22
Survey held at New Union Company
Des. of Damages: FT / Rear / O/S / N/S / U/C / Rooftop or
FT N/S, FT, O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report

Date/Time, File Return to?
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Report Format: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS _____ SI
Photos _____
Others _____

P

Email: numotor@singnet.com

Quote Date: 10-03-2022

Item #	Description	Qty	Unit Price	Discount	Price
1	Side Cover LHS	1	\$ 120.00		\$ 120.00
2	Side Cover RHS	1	120.00		\$ 120.00
3	Front Number Plate	1	25.00		\$ 25.00
4	Wheel Bearings, Front	2	40.00		\$ 80.00
5	Rim Repair	1	120.00		\$ 120.00
6	Rim Shaft, Front	1	65.00		\$ 65.00
7	Brake Lever, LHS	1	29.00		\$ 29.00
8	Brake Lever, RHS	1	29.00		\$ 29.00
9	Signal Lamp, Front - RHS	1	95.00		\$ 95.00
10	Front Cover Upper	1	149.00		\$ 149.00
11	Front Cover Lower	1	89.00		\$ 89.00
12	Cover Floor side, RHS	1	149.00		\$ 149.00
13	Handle Balancer	2	35.00		\$ 70.00
14	Handle Bar	1	150.00		\$ 150.00
15	Handle Grip Rubber	2	20.00		\$ 40.00
16	Front Fender	1	145.00		\$ 145.00
17	Head Lamp Assy	1	450.00		\$ 450.00
18	Brake pump, Hand	1	240.00		\$ 240.00
19	Side Mirror	2	65.00		\$ 130.00
20	Windshield Bracket	1	65.00		\$ 65.00
21	Windshield Visor	1	120.00		\$ 120.00
22	Fork Assy - Repair	1	120.00		\$ 120.00
23	Steering Corn	1	120.00		\$ 120.00
24	Fork Oil	1	20.00		\$ 20.00
25	Fork Seal Set(Pair)	1	60.00		\$ 60.00
26	Pinion Foot Rest, RHS	1	85.00		\$ 85.00
27	Head Lamp Stay Bracket	1	220.00		\$ 220.00
28	Racking, Carrier	1	150.00		\$ 150.00
29	Brake Disc, Front Repair	1	110.00		\$ 110.00
30	Rim Buss, Front	1	35.00		\$ 35.00
					\$ 35.00

cut ✓
cut ✓
x
x
x
x
x
cut ✓
x
cut ✓
cut ✓
cut ✓
cut ✓
bt ✓
x
cut ✓
cut ✓
cut ✓
x
x
x
x
Go ?
x
x
x
x
cut ✓
x
x

Make all checks payable to New Union Company.

Continue next pg

New Union Company

GST Reg No. M90370043N

9004 Tampines Street 93 #01-106
Singapore 528838

P: 67849488
F: 67847588

Email: numotor@singnet.com

Attn: To Whom Concern

Phone:

Quotation No. #:10_03_2022_I

Address: -

Fax:

Quote Date: 10-03-2022

Email:

Quotation For: Bike Repair - FBS3489E

Item #	Description	Qty	Unit Price	Discount	Price
31	Exhaust Cover Protector, Rear	1	\$ 97.00		\$ 97.00
32	Exhaust Cover Protector, Side	1	89.00		\$ 89.00
33	Exhaust Cover Protector, Front	1	78.00		\$ 78.00
34	Exhaust Gasket	1	65.00		\$ 65.00
35	Towing	1	65.00		\$ 65.00
36	Chassis - Repair	1	350.00		\$ 350.00
37	Labour Charge	1	350.00		\$ 350.00
38					\$ -
39					\$ -
40					\$ -
41					\$ -
42					\$ -
43					\$ -
44					\$ -
45					\$ -
46					\$ -
47					\$ -
48					\$ -
49					\$ -
50					\$ -
51					\$ -

int-
b/t ✓
cut-
X
50? towing
use app.
K
200

Sub-Total b/f GST	\$ 4,494.00
Tax Rate	7.00%
GST	314.58
Other	-
Deposit Received	-
Grand Total with GST	\$ 4,808.58

Customer Signature

Make all checks payable to New Union Company.

Taufik 97445749
WP' 9/3/22 @ 520pm
L/S Resurvey of kkn repair
taufik@lkkauto.com.
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: