


17/04/2017 China

ASSIGNMENT

Report
Estimated Cost
CO/TP/MS/TP/FES/OT/FES/EVA/INV/INV
To inspect Vehicle No
at Workshop No
Insured
Policy No
Claimed No
Sum Insured
(Client's Record)
Make of Veh

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal or Market Value
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est Repairs 2 days Res.: Yes or No
Lum Sort % J Val: Yes or No
CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No 511C8884C
Type M Car / M Cycle / Bus / Van / Lorry / ☒ Prime Mover /
Truck / Trailer or

Make Toyota prius
Colour blue
Sp Reading 251491.
Eng No
CNo: 3+04B3FU003091297
Gen Cond. Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim STD A/Rim or
Tyre Size: F: 195/65R15
R: 195/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 16/2/22 D.O.I. 17/2/22 17/5
Survey held at CDGE

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Days Of Report: ☐ : Prel. Report
☐ : Final Report

Days Of Report:
Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : VVA+1 (\$)

Survey Fee:	
Transportation	
S + RS: \$	
Fuels	
Others	
Total	

Request Form 4:
Date: 17/04/2017