

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK - Thevan

DATE: 17-Feb-22

INSURANCE: CHINA TAIPING

CP/P)

MODEL: Toyota Prius

MVA: LIM T S

VEHICLE NO.: SHC8884C

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$458.60 X
	Rear Bumper Re-Inforcement	1		\$318.80 A.
	Rear Bumper Lower Cover-Black	1		\$552.60 /scr
	Rear Bumper Tow Cover	1		\$82.70 /DS
	Rear Bumper Clips	10	\$2.20	\$22.00 /mc
	SUB TOTAL			\$1,434.70
	LESS 25%			\$358.68
	DISCOUNTED TOTAL			\$1,076.03
	Reverse Sensor	1		\$135.70 /qr
	Rear Bumper Mat	1		\$50.00 XSV
	NETT TOTAL			\$185.70
	TOTAL SPARE PARTS			\$1,261.73
	Labour Charge			
	Panel Beating			\$400.00 350
	Spray Painting Charge			\$300.00 250
	Remove/Refix Reverse Sensor			\$120.00 50
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,081.73

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan 82235769

17/2/22 1715

P/P bfr paint photo

2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date/Time: 17.02.2022 15:32

Page : 1

: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4175144

JC NO305505440

IR

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO.: SHC8884C	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A17)	DATE/TIME IN 02.2022 12:10
YR OF MANU. 15.04.2020	TARGET DATE
CHASSIS CODE JTDKB3FU003091297	COMPLETION DATE/TIME:


T CARD NO.

JOB DESCRIPTION

ident Date: 16.02.2022
JRE: 3P 16.02.2022

LABOR CODE
PB

DESCRIPTION
PANEL BEATING-SHC8884C



D & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHC8884C

LIMITS

Vehicle No.:

SHC8884C

Service Advisor

Signature/Date

Name of Service Advisor

Date

Handed to Service Reception upon collection

To be kept by Security Guard