

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                       |  |
|---|--|---|-----------------|-----------------------|--|
|   | GREAT AMERICAN   | N INSURANCE COMPANY   | Ref:            | CS/GAI22002245/Kvy3e2 |  |
|   | 3 TEMASEK AVEN<br>#16-01 CENTENNI<br>SINGAPORE 0391  | AL TOWER  | Date:           | 29/03/2022            |  |
|   |  |   | Code:           | GAI                   |  |
| 1.  | I. Policy Particulars :- THIRD PARTY CLAIM   |   |                 |                       |  |
|   | Insured Veh.   | GBH 5578B   | Veh. Inspected  | SKS 409A              |  |
|   | Policy No.   |   | Coverage (\$)   | 0.00                  |  |
|   | Claim No.  | CLMOMVC000004139  | Excess (\$)     | 0.00                  |  |
|   | Assign From  | SHERY WONG  | Assign Date     | 10/03/2022            |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                       |  |
|   | Make & Model   | HONDA HRV (A)   | c.c             | 1496                  |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    | 2019                  |  |
|   | Chassis No.  | JHMRU1810JX201976   | Colour          | METALLIC LIGHT BROWN  |  |
|   | Odometer   | 68912 KM  | Steering        | IN ORDER              |  |
|   | Brakes   | IN ORDER  | Modification    | STANDARD ALLOY RIM    |  |
|   | General  | GOOD  |                 |                       |  |
| 3. Conditions of Tyres  |  |   |                 |                       |  |
|   |  | Size  | Make            | Balance               |  |
|   | R/H Front Tyre   | 215/60 R16  | DUNLOP          | 5 mm                  |  |
|   | L/H Front Tyre   | 215/60 R16  | DUNLOP          | 5 mm                  |  |
|   | R/H Rear Tyre  | 215/60 R16  | DUNLOP          | 5 mm                  |  |
|   | L/H Rear Tyre  | 215/60 R16  | DUNLOP          | 5 mm                  |  |
| 4.  | Description of Damages   |   |                 |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.   |   |                 |                       |  |
|   | DAMAGES SEE DETAILS.   |   |                 |                       |  |
| 5.  |  | General Information   |                 |                       |  |
|   | Accident Date  | 08/03/2022  | Inspection Date | 10/03/2022            |  |
|   | Survey held at   | POON SIANG SEOW   |                 |                       |  |
|   |  | No.160 SIN MING DRIVE<br>#05-13 SIN MING AUTOCITY<br>SINGAPORE 575722 |                 |                       |  |
| 5a.   | Remarks  |   |                 |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                       |  |
| 5b.   | Estimate Days of Repair  |   |                 |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days   |   |                 |                       |  |